## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Tan Kah Leong Date: 27 Nov 2020

# **Preliminary Advice**

Insured Vehicle No : SMA8790R

TP Vehicle No : PC8491H Accident Date : 24/08/2020 Make : TOYOTA HIACE Assignment Date : 25/08/2020

: 26/08/2020 Date of Inspection Est. Duration of Repair : 5

Inspection At : J-MART MOTOR PTE LTD (HQ)

BLK 5 DEFU LANE 10, #01-578

SINGAPORE 539186

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 8,132.11 |
|-----------------------------|------|----------|
| Revised Amount              | :S\$ | 4,751.76 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 4,751.76 |
|                             |      |          |
| Lump Sum Repair             | :S\$ | 3,800.00 |

#### **Total Loss Consideration**

| New for Old Value  | :S\$ |
|--------------------|------|
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

#### Remarks

| ( | ) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. |
|---|---|--|
|   |   | Kindly let us have your authorisation.   |
|   |   |  |

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: survey on wp ( x )