



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

6 repair days

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Toh Jun Chong ADDRESS : Blk 819 Jurong West Street 81 #08-244 Singapore 640819 TEL : 97651705 / tohjunhong@gmail.com		WIP : EXCESS : DATE: 25-Aug-20	
VEH NO :	SMS2097D	DATE IN :		CONTACT PERSON :	JESS 8128 9802
CHASSIS NO :	JM6GL1072K0321467	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	M6	DATE REG. :	14-Feb-20	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	BODY (L), REAR DOOR <i>repair</i> 1	MGHY1-73-02XB	1,312.10
2	FASTENER (L), WEATHERSTRIP @ 9.20 <i>X nn</i> 1	MGBFN-73-763	9.20
3	WEATHERSTRIP(L) <i>X nn</i> 1	MGBFN-73-760	143.10
4	FASTENER, WEATHERSTRIP(L) @ 3.20 <i>X nn</i> 2	MBBM6-58-762	6.40
5	FASTENER, RUBBER-WEATHER @ 3.40 <i>X nn</i> 25	MBC1D-58-762	85.00
6	STRIPE NO.4(L), BODY SIDE <i>X nn</i> 1	MGRT6-50-8W4A 00	15.50
7	STRIPE NO.2(L), BODY SIDE <i>X nn</i> 1	MGRT6-50-8W2A 00	11.90
8	GROMMET @ 2.40 <i>X nn</i> 4	MBF67-51-261	9.60
9	PIN-CATCH @ 11.00 <i>X nn</i> 2	MBN8F-72-917	22.00
10	FASTENER @ 3.20 <i>X nn</i> 2	MGD7A-50-EA1	6.40
11	CLIPS @ 3.00 <i>X nn</i> 14	MGJ6A-58-975	42.00
12	FASTENER @ 7.20 <i>X nn</i> 9	MGJ6A-68-AB1	64.80
13	PANEL(L), FENDER-REAR <i>repair</i> 1	MGSY7-71-41X	1,312.50
14	MOULD, RR WINDOW <i>X nn</i> 1	MGHK1-50-611B	117.10
15	SPACER @ 12.80 <i>X nn</i> 1	MGJ6A-50-897	12.80
16	TERMINAL, GLASS-BACK @ 30.60 <i>X nn</i> 3	MFB01-63-959	91.80
17	BUMPER, REAR <i>repair</i> 1	MGSK1-50-221A BB	1,099.00
18	TAPE, PROTECTOR @ 4.70 <i>X nn</i> 4	MBCKA-50-EM1	18.80
19	RIVETS @ 9.20 <i>X nn</i> 2	MTK21-50-355	18.40
20	CLIPS @ 4.60 <i>X nn</i> 6	MGHK1-51-SJ3	27.60
21	CLIPS, DR GARNISH @ 12.30 <i>X nn</i> 6	MKD53-50-M38	73.80
22	GUARD (L), STONE-REAR @ 17.40 <i>nn</i> 1	MGHP9-50-4R2A	17.40
23	CLIPS, GARNISH SIDE SILL @ 10 <i>X nn</i> 13	MBP4L-51-SJ3	130.00
24	CLIPS, GARNISH SIDE SILL @ 6.50 <i>X nn</i> 2	MG18K-51-SJ3	13.20
25	WHEEL, DISC @ 1196.80 <i>scr</i> 1	M99651-67570	1,196.80
26	VALVE, AIR @ 6.70 <i>nn</i> 1	M99636-04140	6.70
TOTAL PARTS			-
TOTAL PARTS COST			-
			5,863.90

Labour Description			
1	MZ-BR-SIDE04	REPLACE LHR DOOR, LHR FENDER, REAR BUMPER. REPAIR AREAS AFFECTED BY THE ACCIDENT.	1320 3,960.00
2	MZ-SP-SSIDE4	SPRAY REAR BUMPER, LHR DOOR, LHR FENDER, LH SIDE SILL.	1890 2,835.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	Xnn 180.00
4	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	NETT Xnn 560.00
5	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	NETT Xnn 120.00
6	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	80 120.00
7	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT 560.00
8	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	Xnn 660.00
9	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	Xnn 660.00
10	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150 250.00
11		TO SUPPLY BRILA PREMIUM COATING (minimize) 80(per panel x 3	? 240 300.00
12	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	40 250.00
13	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180 350.00
14	MZ-BR-SUNDRI	SUNDRIES.	10 100.00
TOTAL LABOUR			- 10,905.00
TOTAL PARTS			- 5,863.90
TOTAL			- 16,768.90
LESS EXCESS			- -
TOTAL AFTER EXCESS			- -
GST 7%			- -
GRAND TOTAL			- -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS

TRANS EUROKARS PTE LTD