



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

to Fui For
SUMMARY.

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Toh Jun Chong ADDRESS : Blk 819 Jurong West Street 81 #08-244 Singapore 640819 TEL : 97651705 / tohjunichong@gmail.com		WIP : EXCESS : DATE: 25-Aug-20	
VEH NO :	SMS2097D	DATE IN :		CONTACT PERSON :	JESS 8128 9802
CHASSIS NO :	JM6GL1072K0321467	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	M6	DATE REG.:	14-Feb-20	POLICY NO. :	
<u>NATURE OF WORKS</u>					
<u>Parts Description</u>					
NO	QTY	REVISED	PRICES		
1	BODY (L), REAR DOOR <i>repair</i>	1	MGHY1-73-02XB		1,312.10
2	FASTENER (L), WEATHERSTRIP @ 9.20 <i>X</i>	1	MGBFN-73-763		9.20
3	WEATHERSTRIP(L) <i>X</i>	1	MGBFN-73-760		143.10
4	FASTENER, WEATHERSTRIP(L) @ 3.20 <i>X</i>	2	MBBM6-58-762		6.40
5	FASTENER, RUBBER-WEATHER @ 3.40 <i>X</i>	25	MBC1D-58-762		85.00
6	STRIPE NO.4(L), BODY SIDE <i>X</i>	1	MGR16-50-8W4A 00		15.50
7	STRIPE NO.2(L), BODY SIDE <i>X</i>	1	MGR16-50-8W2A 00		11.90
8	GROMMET @ 2.40 <i>X</i>	4	MBF67-51-261		9.60
9	PIN-CATCH @ 11.00 <i>X</i>	2	MBN8F-72-917		22.00
10	FASTENER @ 3.20 <i>X</i>	2	MGD7A-50-EA1		6.40
11	CLIPS @ 3.00 <i>X</i>	14	MGJ6A-58-975		42.00
12	FASTENER @ 7.20 <i>X</i>	9	MGJ6A-68-AB1		64.80
13	PANEL(L), FENDER-REAR <i>repair</i>	1	MGSY7-71-41X		1,312.50
14	MOULD, RR WINDOW <i>X</i>	1	MGHK1-50-611B		117.10
15	SPACER @ 12.80 <i>X</i>	1	MGJ6A-50-897		12.80
16	TERMINAL, GLASS-BACK @ 30.60 <i>X</i>	3	MFB01-63-959		91.80
17	BUMPER, REAR <i>repair</i>	1	MGSK1-50-221A BB		1,099.00
18	TAPE, PROTECTOR @ 4.70 <i>X</i>	4	MBCKA-50-EM1		18.80
19	RIVETS @ 9.20 <i>X</i>	2	MTK21-50-355		18.40
20	CLIPS @ 4.60 <i>X</i>	6	MGHK1-51-SJ3		27.60
21	CLIPS, DR GARNISH @ 12.30 <i>X</i>	6	MKD53-50-M38		73.80
22	GUARD (L), STONE-REAR @ 17.40 <i>na</i>	1	MGHP9-50-4R2A		17.40
23	CLIPS, GARNISH SIDE SILL @ 10 <i>X</i>	13	MBP4L-51-SJ3		130.00
24	CLIPS, GARNISH SIDE SILL @ 6.50 <i>X</i>	2	MG18K-51-SJ3		13.20
25	WHEEL, DISC @ 1196.80 <i>scr</i>	1	M99651-67570		1,196.80
26	VALVE, AIR @ 6.70 <i>na</i>	1	M99636-04140		6.70
TOTAL PARTS				-	5,863.90
TOTAL PARTS COST				-	-
TOTAL PARTS COST				-	5,863.90

Labour Description			
1	MZ-BR-SIDE04	REPLACE LHR DOOR, LHR FENDER, REAR BUMPER. REPAIR AREAS AFFECTED BY THE ACCIDENT.	1320 3,960.00
2	MZ-SP-SSIDE4	SPRAY REAR BUMPER, LHR DOOR, LHR FENDER, LH SIDE SILL.	1890 2,835.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	X 180.00
4	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	NETT X 560.00
5	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	NETT X 120.00
6	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	80 120.00
7	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT 560.00
8	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	X 660.00
9	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	X 660.00
10	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150 250.00
11		TO SUPPLY BRILA PREMIUM COATING (minimize) 80(per panel) x 3	? 300.00
12	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	40 250.00
13	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180 350.00
14	MZ-BR-SUNDRI	SUNDRIES.	10 100.00

TOTAL LABOUR	-	10,905.00
TOTAL PARTS	-	5,863.90
TOTAL	-	16,768.90
LESS EXCESS	-	-
TOTAL AFTER EXCESS	-	-
GST 7%	-	-
GRAND TOTAL	-	-

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS

TRANS EUROKARS PTE LTD

Pam

Hq 90010068

6 days

26/08/2020 @ 1430

Resurvey after repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: