

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE

SINGAPORE 068877

INV No. AC2007321

INV Date 03/11/2020

Reference CC4/FCI20008998/Uka3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SCA 6119L

Insured Veh. SHC 608L

Claim No. D20003376MFSH/1

Policy No. D-20094921MFSH

Accident Date 23/08/2020

Inspection Date 01/09/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile			
MS F	S FIRST CAPITAL INSURANCE LTD Ref: CC4/FCI20008998/Uka3q2			
	OBINSON ROAD 01 CITY HOUSES	INGAPORE 068877	Date: 03-11-2020 Code: FCI2	
1.		Policy Particulars	:- THIRD PARTY CLAIM	
	Insured Veh.	SHC 608L	Veh. Inspected	SCA 6119L
	Policy No.	D-20094921MFSH	Coverage (\$)	0.00
	Claim No.	D20003376MFSH/1	Excess (\$)	0.00
	Assign From	ERIC WOO	Assign Date	25/08/2020
2.		Vehicle Partic	culars & Condition	
	Make & Model HONDA CIVIC (A) c.c 1597			1597
	Engine No.	HIDDEN	Year of Reg. 2019	
	Chassis No.	MRHFC5650JT002173	Colour	GREY
	Odometer	22064	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Condition	ons of Tyres	
	Size Make Balance			Balance
	R/H Front Tyre	215/55 R16	HANKOOK	6 mm
	L/H Front Tyre	215/55 R16	HANKOOK	6 mm
	R/H Rear Tyre	215/55 R16	HANKOOK	6 mm
	L/H Rear Tyre	215/55 R16	HANKOOK	6 mm
4.		Description	on of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		General	Information	
	Accident Date	23/08/2020	Inspection Date	01/09/2020
	Survey held at	KAH MOTOR CO SDN BERHAD)	
		15 UBI ROAD 4 SINGAPORE 408610		
5a.		Re	emarks	
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCA 6119L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILLIGHT,ASSYR (SN)	NOT NECESSARY	214.12	-
1	TAILLIGHT,ASSYL (SN)	NOT NECESSARY	230.55	-
1	BEAM COMPRR.BUMPER (SN)	DENTED	135.00	135.00
1	SPACERR.RR.BUMPER SIDE (SN)	NOT NECESSARY	8.62	-
1	SPACERL.RR.BUMPER SIDE (SN)	NOT NECESSARY	8.62	-
1	GARNISH,RR,BUMPER LOWER (SN)	CUT	29.85	29.85
1	COVERRR.TOWING HOOK (SN)	NOT NECESSARY	6.67	-
1	BRACKETR.RR.BUMPER SIDE (SN)	NOT NECESSARY	1.87	-
1	BRACKETL.RR.BUMPER SIDE (SN)	NOT NECESSARY	1.87	-
1	FACE ASSY,RR.BUMPER (SN)	DENTED / DEFORMED	462.90	462.90
1	PANEL SETRR (SN)	TO REPAIR SEE LABOUR	199.27	-
1	STIFFENER,R.RR.PANEL SIDE (SN)	NOT NECESSARY	21.90	-
1	STIFFENERL,RR.PANEL SIDE (SN)	NOT NECESSARY	21.90	-
1	LID COMP TRUNK (SN)	NOT NECESSARY	398.40	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	BODY JOINT SEALANT (SN)	NOT NECESSARY	100.00	-
			1,891.54	647.75
	<u>LABOUR</u>			
	BODY UNDERSIDE COATING.	NOT NECESSARY	100.00	-
	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER.		160.00	120.00
	REMOVE & INSTALL REVERSE SENSORS-4 PCS.		240.00	140.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.	NOT NECESSARY	380.00	-
	RESET VEHICLE SMART ENTRY SYSTEM.	NOT NECESSARY	450.00	-
	REMOVE & INSTALL REAR COMPARTMENT LININGS.	NOT NECESSARY	450.00	-
	STRAIGHTEN ALIGN TRUNK LID.	NOT NECESSARY	550.00	-
	CUT & RENEW RR PANEL,GUTTER AND RR FENDER.INCLUSIVE OF THE REPAIR OF PANEL SETRR.		2,800.00	975.00

Report Ref No. CC4/FCI20008998/Uka3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P).		3,200.00	1,040.00
			8,330.00	2,275.00
	GRAND TOTAL		10,221.54	2,922.75

RECOMMENDED COST OF REPAIRS			2,922.75
-----------------------------	--	--	----------

Report Ref No. CC4/FCI20008998/Uka3q2

CHUA KANG SENG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SCA 6119L

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi hdustrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi hdustrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SCA 6119L













