

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118007761/GZ4BS2  
Date: 02/08/2018

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3047111802
Claimant Vehicle No :	SJQ5323C	Insured Vehicle No :	SKP2016C
Date of Loss:	26/04/2018	Nature of Claim:	TP
			Claim No: SNM18D02144C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ5323C	Engine No:	Z6795689
Make & Model:	MAZDA 3, 1.6 LUX (A)	Chassis No:	JM6BL10Z1A0105478
Reg. Date:	15/05/2009 (Man. Year: 2009)	Odometer:	178193 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

### INSPECTION

Date of Assignment:	27/04/2018		
Date Inspected:	27/04/2018	Inspected At:	Neo Automotive Pte Ltd (HQ) 53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL PARK Singapore 408934
Estimated Period of Repair:	7.0 days		

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 31 Jul 2018)  
**Parts:** 143      **MAZDA 3 1.6 LUX (A) (Catalogue:Merimen Singapore 1.0)**  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** LKK Auto Consultants Pte Ltd/SJQ5323C/02/08/2018 10:36  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

LKK Auto Consultants Pte Ltd/SJQ5323C/02/08/2018 10:36. Not valid without Reference section.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

LKK Auto Consultants Pte Ltd/SJQ5323C/02/08/2018 10:36. Not valid without Reference section.
--

< END OF ESTIMATES >

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7964061A



Name

SHA QI

沙 琪

Race

CHINESE

Date of birth

12-11-1979

Sex

M

S7964061A

Country/Place of birth

CHINA



5576141



NRIC No. S7964061A



Date of issue

17-03-2016

281 JOO CHIAT PLACE #03-04  
SINGAPORE 427962

NRIC No: S7964061A

Date: 14/12/2019