Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20009001/EQF3E2

Date: 31/08/2020

REFERENCE

No:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 099993970 Claimant Vehicle SJS5592G **Insured Vehicle No:** SJX3864J

ΤP Date of Loss: 21/08/2020 Nature of Claim: Claim No: 4243103021SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS5592G

Make & Model: HONDA STREAM, 1.8 RSZ (A) Engine No: R18A1793282 Reg. Date: 24/08/2009 (Man. Year: 2008) Chassis No: RN61084072 Colour: Odometer: 132738 km White

Engine Capacity: 1799 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

215/45 R17 Front Tyre Size: 215/45 R17 Rear Tyre Size: Front Left Side: Rear Left Side: Michelin 5 mm Michelin 5 mm Rear Right Side: Front Right Side: Michelin 5 mm Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/08/2020

Date Inspected: 26/08/2020 Inspected At: Garage 13 Pte. Ltd. (HQ)

8 Kaki Bukit Avenue 4, #03-46 Premier

Singapore 415875

Estimated Period of Repair: 3.0 days

CHEN TSUE YEE Adjuster: Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Broken	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*FRT LH BUMPER FOG LAMP COVER	Cut	0.00 F	*- F
5	1		*FRT LH HEADLAMP ASSY	Cut	0.00 F	*- F
6	1		*LH HEADLAMP BRACKET	Broken	0.00 F	*- F
7	1		*FRT LH FENDER	Repair	0.00 F	*- F
F=Fra	anchise	part.		_		
				Total Parts (S\$)	0.00	0.00
r F=Fra	ı anchise	part.	FRI LII FENDER	· –		

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >