

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009002/UPS3Q2
Date: 10/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100399256
Claimant Vehicle No :	SKG2990L	Insured Vehicle No :	SKR534B
Date of Loss:	21/08/2020	Nature of Claim:	TP
		Claim No:	7664619447SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG2990L	Engine No:	CAV420007
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 TSI (A)	Chassis No:	WVWZZZ13ZCV038450
Reg. Date:	21/08/2012 (Man. Year: 2012)	Odometer:	149238 km
Colour:	White		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,377.56	952.40	1,425.16	59.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	690.00	910.00	56.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,977.56	1,642.40	2,335.16	58.71
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	3,977.56	1,300.00	2,677.56	67.32
+ GST 7.00/7.00% (S\$)	278.43	91.00	187.43	67.32
Nett Amount (S\$)	4,255.99	1,391.00	2,864.99	67.32
+ Car Rental (4.5 x S\$100.00/day) (S\$)		450.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,843.00		
Global Sum Settlement (S\$)		1,820.00		

INSPECTION

Date of Assignment:	26/08/2020		
Date Inspected:	26/08/2020	Inspected At:	Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	720.00 FL	*720.00 FL
2	1		*REAR BUMPER TOP RETAINER	Cracked	116.00 FL	*116.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Repair	390.00 FL	*- FL
4	1		*REAR END PANEL	Repair	756.20 FL	*- FL
5	1		*REAR TAIL LAMP -RH	Not Necessary	326.20 FL	*- FL
6	1		*SET REAR BUMPER SENSOR	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,608.40	1,036.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	230.84	83.60
Total Parts (\$\$)	2,377.56	952.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	750.00	220.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	0.00
4	TO REMOVE & REPLACE BUMPER SENSOR	New	80.00	50.00
5	TO SPRAY PAINT	New	650.00	400.00
Gross Labour Cost (S\$)			1,600.00	690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >