

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT120009009/QSF3E2

Date: 16/09/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00038442000

Claimant Vehicle No : SMA8353U

Insured Vehicle No : SLW7501L

Date of Loss: 24/08/2020

Nature of Claim: TP

Claim No: SNM20D203026C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA8353U**

Make & Model: HYUNDAI ELANTRA, 1.6 (A)

Engine No: G4FGJU205884

Reg. Date: 21/06/2018 (Man. Year: 2018)

Chassis No: KMHD841CMJU705121

Colour: White

Odometer: 44564 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 215/45Z R17 | Rear Tyre Size: | 215/45Z R17 |
| Front Left Side: | Nexen 6 mm | Rear Left Side: | Nexen 6 mm |
| Front Right Side: | Nexen 6 mm | Rear Right Side: | Nexen 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 12,201.29 | 2,145.27 | 10,056.02 | 82.42 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,500.00 | 1,060.00 | 3,440.00 | 76.44 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 16,701.29 | 3,205.27 | 13,496.02 | 80.81 |
| Approved Total (Overridden) (S\$) | | 2,550.00 | | |
| (S\$) | 16,701.29 | 2,550.00 | 14,151.29 | 84.73 |
| + GST 7.00/7.00% (S\$) | 1,169.09 | 178.50 | 990.59 | 84.73 |
| Nett Amount (S\$) | 17,870.38 | 2,728.50 | 15,141.88 | 84.73 |

INSPECTION

Date of Assignment: 25/08/2020

Date Inspected: 26/08/2020 Inspected At:

Vermogen Ace Pte Ltd (Jln Lam Huat) (HQ)
60 Jalan Lam Huat, #03-35/36
Singapore 737869

Estimated Period of Repair: 4.0 days

Adjuster: OI SUN PIN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 16 Sep 2020) |
| Parts: 143 | HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SMA8353U) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|-------------|-------------|--------------|
| 1 | 1 | | *BONNET | Repair | 1,910.30 FL | *- FL |
| 2 | 2 | | *BONNET HINGES LH / RH | Serviceable | 98.20 FL | *- FL |
| 3 | 1 | | *BONNET HEAT INSULATOR | Serviceable | 221.10 FL | *- FL |
| 4 | 1 | | *SET BONNET HEAT INSULATOR CLIPS | Serviceable | 20.00 FL | *- FL |
| 5 | 1 | | *BONNET LOCK | Serviceable | 129.90 FL | *- FL |
| 6 | 1 | | *FRONT BUMPER | Crumpled | 474.40 FL | *474.40 FL |
| 7 | 1 | | *SET FRONT BUMPER CLIPS | Necessary | 25.00 FL | *25.00 FL |
| 8 | 2 | | *FRONT BUMPER RETAINER LH / RH | Necessary | 56.00 FL | *56.00 FL |
| 9 | 1 | | *FRONT BUMPER CENTER RUBBER | Serviceable | 29.40 FL | *- FL |
| 10 | 1 | | *FRONT BUMPER GRILL LOGO | Necessary | 25.00 FL | *25.00 FL |
| 11 | 1 | | *FRONT BUMPER GRILL | Cracked | 495.80 FL | *495.80 FL |
| 12 | 1 | | *FRONT BUMPER LOWER GARNISH | Serviceable | 127.00 FL | *- FL |
| 13 | 1 | | *FRONT BUMPER STIFFINER | Crumpled | 63.70 FL | *63.70 FL |
| 14 | 1 | | *FRONT BUMPER SPONGE | Crumpled | 110.70 FL | *110.70 FL |
| 15 | 1 | | *FRONT BUMPER REINFORCEMENT | Repair | 695.80 FL | *- FL |
| 16 | 1 | | *FRONT SUPPORT PANEL | Serviceable | 949.30 FL | *- FL |
| 17 | 1 | | *FRONT SUPPORT TOP COVER | Crumpled | 77.10 FL | *77.10 FL |
| 18 | 1 | | *SET FRONT SUPPORT TOP COVER CLIPS | Necessary | 25.00 FL | *25.00 FL |
| 19 | 2 | | *FOG LAMP LH / RH | Serviceable | 530.20 FL | *- FL |
| 20 | 2 | | *FOG LAMP CHROME RING LH / RH | Serviceable | 230.80 FL | *- FL |
| 21 | 2 | | *FOG LAMP GARNISH LH / RH | Serviceable | 130.00 FL | *- FL |
| 22 | 1 | | *TOW HOOK COVER | Scratched | 25.00 FL | *25.00 FL |
| 23 | 1 | | *FRONT UNDERNEAT COVER | Serviceable | 173.29 FL | *- FL |
| 24 | 1 | | *SET FRONT UNDERNEAT COVER CLIPS | Serviceable | 25.00 FL | *- FL |
| 25 | 1 | | *HEAD LAMP LH / RH | O/S Cracked | 2,397.60 FL | *1,198.80 FL |
| 26 | 2 | | *HEAD LAMP RUBBER LH / RH | Serviceable | 127.00 FL | *- FL |
| 27 | 1 | | *HEAD LAMP LOWER BRACKET LH / RH | O/S Cracked | 75.40 FL | *37.70 FL |
| 28 | 2 | | *FRONT FENDER LH / RH | Serviceable | 2,455.40 FL | *- FL |
| 29 | 2 | | *FRONT FENDER INNER SHIELD LH / RH | Serviceable | 205.68 FL | *- FL |
| 30 | 2 | | *SET FRONT FENDER INNER SHIELD CLIPS | Serviceable | 40.00 FL | *- FL |
| 31 | 1 | | *WASHER TANK | Serviceable | 70.80 FL | *- FL |
| 32 | 1 | | *CONDENSER | Serviceable | 745.10 FL | *- FL |
| 33 | 1 | | *RADIATOR | Serviceable | 510.50 FL | *- FL |
| 34 | 1 | | *AIRCON PIPE | Serviceable | 257.00 FL | *- FL |
| 35 | 1 | | *AIRCON SUCTION PIPE | Serviceable | 630.30 FL | *- FL |
| 36 | 1 | | *AIRCON DISCHARGE PIPE | Serviceable | 200.20 FL | *- FL |
| 37 | 1 | | *FAN COWLING | Serviceable | 567.50 FL | *- FL |
| 38 | 1 | | *FAN MOTOR | Serviceable | 235.00 FL | *- FL |
| 39 | 1 | | *FRONT NUMBER PLATE BASE | Crumpled | 23.64 FL | *23.64 FL |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|--|-----|----------|---------------------|-----------|--|------------------|-----------------|
| 40 | 1 | | *FRONT NUMBER PLATE | Dented | 50.00 FS | *35.00 FS | |
| F=Franchise part. S=SpcNett. L=ListItemDisc. | | | | | | | |
| | | | | | Sub Total (\$) | 15,239.11 | 2,672.84 |
| | | | | | - List Item Discount on L Items 20.00/20.00% (\$) | 3,037.82 | 527.57 |
| | | | | | Total Parts (\$) | 12,201.29 | 2,145.27 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA. RH PORTION. BONNET, FRONT BUMPER, FRONT BUMPER REINFORCEMENT, FRONT SUPPORT PANEL, FRONT FENDER LH / RH | New | 2,000.00 | 500.00 |
| 2 | TO PUTTY, RESPRAY PAINTING AND POLISH ACCIDENT AREA. RH PORTION. BONNET, FRONT BUMPER, FRONT BUMPER REINFORCEMENT, FRONT SUPPORT PANEL, FRONT FENDER LH / RH | New | 2,000.00 | 500.00 |
| 3 | TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT | New | 100.00 | 30.00 |
| 4 | TO RUST PROOF AFFECTED AREAS | New | 100.00 | 30.00 |
| 5 | TO REMOVE AND REFIT INTERIOR PARTS TO GIVE WAY THE REPAIR | New | 200.00 | 0.00 |
| 6 | TOP UP AIRCON GAS | New | 100.00 | 0.00 |
| Gross Labour Cost (S\$) | | | 4,500.00 | 1,060.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >