

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20009010/R1TF3E2

Date: 28/09/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00011892005

Claimant Vehicle No : SMP5161Y

Insured Vehicle No : SQ7S

Date of Loss: 21/08/2020

Nature of Claim: TP

Claim No: SNM20D203005C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP5161Y**

Make & Model: BMW X2, 1.5 SDRIVE18I (A)

Engine No: 41015740B38B15A

Reg. Date: 30/09/2019 (Man. Year: 2019)

Chassis No: WBAJG120405N81554

Colour: Grey

Odometer: 8780 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,276.10	2,390.65	1,885.45	44.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,310.00	5,107.00	1,203.00	19.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,586.10	7,497.65	3,088.45	29.17
+ GST 7.00/7.00% (S\$)	741.03	524.84	216.19	29.17
Nett Amount (S\$)	11,327.13	8,022.49	3,304.64	29.17

INSPECTION

Date of Assignment: 26/08/2020

Date Inspected: 14/09/2020 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Sep 2020)
Parts:	M1-SUV	BMW X2 1.5 SDRIVE18I (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP5161Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*BOOTLID	Bent	1,236.65 FS	*1,236.65 FS
3	1		*RR BUMPER CARRIER	Serviceable	496.35 FS	*- FS
4	1		*REAR BUMPER TRIM PANEL BOTTOM (BASI	Deformed	206.85 FS	*206.85 FS
5	1		*MOUNTING SMART OPENER	Serviceable	45.55 FS	*- FS
6	1		*# RR BUMPER LH CORNER MOUNTING	Serviceable	142.65 FS	*- FS
7	1		*# RR BUMPER RH CORNER MOUNTING	Serviceable	142.65 FS	*- FS
8	1		*REAR BUMPER PANEL PRIMED	Repair	903.40 FS	*- FS
9	1		*# REAR BUMPER MIDDLE TRIM PANE	Scratched	265.65 FS	*265.65 FS
10	2		*EMBLEM GROMMET	Necessary	1.70 FS	*1.70 FS
11	1		*BMW PLAQUE WITH ADHESIVE FILM	Necessary	71.60 FS	*71.60 FS
12	1		*LETTERING X1	Necessary	64.45 FS	*64.45 FS
13	1		*BUMP STOP (10PCS)	Necessary (6Pcs Only)	37.50 FS	*22.50 FS
14	1		*# REAR BUMPER HEAT INSULATION	Serviceable	69.85 FS	*- FS
15	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
16	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
17	5		*BLIND RIVET NUT M6	Necessary	13.50 FS	*13.50 FS
18	10		*EXPANDING RIVET BLACK	Necessary	14.00 FS	*14.00 FS
19	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML	Necessary	27.85 FS	*27.85 FS
20	1		*LETTERING S DRIVE 18I	Necessary	96.65 FS	*96.65 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,276.10** **2,390.65**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER, BOOT LID INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	2,550.00	1,700.00
2	TO RESPRAY REAR BUMPER AND BOOT LID	New	2,006.00	1,805.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
4	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO TRANSFER FROM OLD TO NEW BOOT LID	New	676.00	676.00
5	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
6	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
7	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
8	TO CONDUCT WATER LEAK TEST	New	75.00	75.00
Gross Labour Cost (S\$)			6,310.00	5,107.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >