



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 8646T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	459.40	459.40
1	REAR BUMPER CTR MOULDING	CRACKED	451.25	451.25
1	REAR BUMPER LWR MOULDING	NOT NECESSARY	155.00	-
1	REAR BUMPER FOGLAMP	NOT NECESSARY	201.50	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-257.83	-186.53
			1,031.32	746.12
	<u>NETT ITEMS</u>			
1	REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
	LESS 10% DISCOUNT		-18.00	-18.00
			162.00	162.00
	<u>LABOUR</u>			
	PANEL BEATING.		350.00	320.00
	SPRAY PAINT CHARGE.		250.00	200.00
	R/I REVERSE SENSOR.		120.00	30.00
			720.00	550.00
GRAND TOTAL			1,913.32	1,458.12
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,458.12

Report Ref No. NS/INC20009012/T1qf3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.