

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20009016/USF3E2
Date: 15/09/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 1001402332
Claimant Vehicle No : SJU5293J	Insured Vehicle No : SLL5333B
Date of Loss: 24/08/2020	Nature of Claim: TP Claim No: 247004

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU5293J	
Make & Model:	TOYOTA WISH, 2.0 (A)	Engine No: 3ZRA422311
Reg. Date:	15/12/2009 (Man. Year: 2009)	Chassis No: JTDGJ20W505001658
Colour:	Brown	Odometer: 190163 km
Engine Capacity:	1987 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,660.52	5,951.25	6,709.27	52.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,500.00	2,820.00	680.00	19.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,160.52	8,771.25	7,389.27	45.72
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	16,160.52	7,000.00	9,160.52	56.68

INSPECTION

Date of Assignment:	26/08/2020	
Date Inspected:	26/08/2020 Inspected At:	15 KAKI BUKIT ROAD 4, #01-53 BARTLEY BIZ CENTER Repairer : Eco Automobile Claims & Repair Pte Ltd - Bartley Biz Center (HQ)
Estimated Period of Repair:	7.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Sep 2020)

Parts: M1-MPV TOYOTA WISH 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJU5293J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,575.90 FL	*1,429.10 FL
2	2		*TAILGATE DAMPER	Not Necessary	422.20 FL	*- FL
3	1		*TAILGATE TOYOTA DAMPER	Necessary	85.50 FL	*68.10 FL
4	1		*TAILGATE INNER LOCK	Dented / Shorted	428.00 FL	*399.20 FL
5	1		*TAILGATE LOCK ACTUATOR	Not Necessary	328.00 FL	*- FL
6	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	520.00 FL	*428.10 FL
7	1		*TAILGATE REAR WINDSCREEN MOULDING (UPPER)	Necessary	162.00 FL	*128.10 FL
8	2		*TAILGATE REAR WINDSCREEN MOULDING (SIDE)	No such part	184.00 FL	*- FL
9	1		*TAILGATE CENTRE CHROME GARNISH	Cracked	292.00 FL	*292.00 FL
10	1		*TAILGATE TAILLAMP LHS & RHS	O/S Cracked	840.00 FL	*408.10 FL
11	1		*TAILGATE WIPER MOTOR	Not Necessary	580.00 FL	*- FL
12	1		*TAILGATE WIPER ARM	Not Necessary	74.00 FL	*- FL
13	1		*TAILGATE WIPER BLADE	Not Necessary	48.20 FL	*- FL
14	1		*TAILGATE WIPER ARM HEAD	Not Necessary	30.00 FL	*- FL
15	1		*REAR BUMPER	Distorted	1,245.00 FL	*588.20 FL
16	2		*REAR BUMPER REFLECTOR	Not Necessary	132.00 FL	*- FL
17	1		*REAR BUMPER SIDE RETAINERS	O/S Bent	180.00 FL	*78.10 FL
18	2		*REAR BUMPER BRACKETS	Not Necessary	190.00 FL	*- FL
19	2		*REAR END PANEL DAMPERS	Not Necessary	197.00 FL	*- FL
20	1		*END PANEL LOCK CATCH	Not Necessary	80.00 FL	*- FL
21	1		*REAR END PANEL TOP GARNISH	Twisted	382.00 FL	*382.00 FL
22	1		*BOOT WEATHERSTRIP	Twisted	249.00 FL	*249.00 FL
23	2		*TAILLAMP RHS & LHS	Cracked	1,578.40 FL	*1,178.20 FL
24	1		*REAR FLOOR PANEL	Repair	1,120.00 FL	*- FL
25	1		*REAR FENDER INNER TRIMBOARD	O/S Torn	1,964.00 FL	*645.10 FL
26	1		*REAR FENDER INNER SPLASH SHIELD LHS & RHS	O/S Torn	476.00 FL	*166.10 FL
27	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	298.00 FL	*- FL
28	1		*REAR END PANEL OUTER	Badly Dented	720.00 FL	*650.10 FL
29	1		*REAR END PANEL LOWER MEMBER	Badly Dented	360.00 FL	*245.50 FL
30	2		*REAR END PANEL CENTRE BRACKETS	No such part	176.00 FL	*- FL
31	1		*REAR EXHAUST	Repair	683.50 FL	*- FL
32	2		*LHS & RHS REAR FENDER GLASS SEALANT	Not Necessary	150.00 FS	*- FS
33	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
34	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
35	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
36	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	60.00 FS	*40.00 FS
37	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*SET REVERSE SENSORS	Shorted	280.00 FS	*200.00 FS
39	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
40	1		*REAR LICENCE PLATE WITH HOLDER	Damaged	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,560.70	7,785.00
- List Item Discount on L Items 25.00/25.00% (\$)	3,900.18	1,833.75
Total Parts (\$)	12,660.52	5,951.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,400.00	1,280.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS	New	1,200.00	1,180.00
3	TO REMOVE / REFIX INNER TRIMS, FITTINGS, GARNISH ETC AT REAR SO AS TO FACILITATE REPAIRS AND REFIX / REPLACE THE SAME	New	250.00	80.00
4	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS, CHECK FOR PROPER FUNCTION	New	200.00	30.00
5	TO REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
6	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTION	New	100.00	50.00
7	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	200.00	80.00
Gross Labour Cost (S\$)			3,500.00	2,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >