



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 8818K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT MUDGUARD (CONSISTENT)	BROKEN	185.00	185.00
1	FRONT RIM (CONSISTENT)	BROKEN	250.00	250.00
1	BRAKE DISC (CONSISTENT)	BENT	200.00	200.00
1	BRAKE PUMP (CONSISTENT)	NOT NECESSARY	250.00	-
1	SET FORK TUBE (CONSISTENT)	BENT	350.00	350.00
1	FORK UNDERBRACKET (CONSISTENT)	BENT	190.00	190.00
1	FORK OIL SEAL (CONSISTENT)	NECESSARY	125.00	125.00
1	RADIATOR (CONSISTENT)	BENT	490.00	490.00
1	HANDLE BAR (CONSISTENT)	BENT	125.00	125.00
1	HANDLE BAR BRACKET (CONSISTENT)	BENT	155.00	155.00
1	HEAD LAMP (CONSISTENT)	BROKEN	320.00	320.00
1	HEAD LAMP COVER (CONSISTENT)	BROKEN	190.00	190.00
2	FRONT SIGNAL LAMP (CONSISTENT)	BROKEN	150.00	150.00
1	METER COVER (CONSISTENT)	BROKEN	120.00	120.00
1	FRONT PANEL CENTRE (CONSISTENT)	BROKEN	190.00	190.00
2	FRONT SIDE PANEL L/RH (CONSISTENT)	BROKEN	290.00	290.00
1	INNER LEG SHIELD (CONSISTENT)	BROKEN	135.00	135.00
2	SIDE PANEL INNER HOLDER (CONSISTENT)	BROKEN	200.00	200.00
1	IGNITION SWITCH (CONSISTENT)	NOT NECESSARY	180.00	-
1	SET MIRROR (CONSISTENT)	BROKEN	120.00	120.00
1	CENTRE GARNISH COVER (CONSISTENT)	BROKEN	165.00	165.00
2	CENTRE-V PANEL (CONSISTENT)	BROKEN	160.00	160.00
2	REAR TAIL PANEL LH/RH (CONSISTENT)	CUT	270.00	270.00
1	EXHAUST PIPE (CONSISTENT)	BENT	250.00	250.00
1	EXHAUST GUARD (CONSISTENT)	NOT NECESSARY	190.00	-
1	ENGINE COVER RH (CONSISTENT)	NOT NECESSARY	220.00	-
1	FOOTREST (CONSISTENT)	SERVICEABLE	65.00	-
1	REAR TAIL LAMP (CONSISTENT)	NOT NECESSARY	165.00	-
1	REAR MUDGUARD (CONSISTENT)	NOT NECESSARY	185.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-588.50	-463.00
			5,296.50	4,167.00
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	NECESSARY	15.00	15.00
1	REAR BOX (SN) (CONSISTENT)	CUT	180.00	180.00
1	METER ASSY (SN) (CONSISTENT)	BROKEN	650.00	650.00
			845.00	845.00
	<u>LABOUR</u>			
	TOWING FEE.	NOT NECESSARY	50.00	-
	REMOVE & REPLACE PARTS,ALIGN & ETC.		350.00	200.00
	REMOVE & REPLACE FORK ASSY,RIM,BRAKE PUMP & DISC,SUPPLY BRAKE OIL,ETC.		200.00	150.00
	RE-CONNECT HARENESS WIRING.		120.00	20.00
	SUPPLY BODY SET DECAL STICKER.		120.00	80.00
	ALIGN BODY FRAME.		280.00	150.00
			1,120.00	600.00
GRAND TOTAL			7,261.50	5,612.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,500.00

Report Ref No. CC4/ASM20009024/Db3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.