

ASSIGNMENT

COE Sept 2020

From: _____ Date: _____

Estimated Cost _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBD 8818K Yr Regn: Sept 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Yamaha T135 C.C. 135

Colour: Red / Black A/C: Insured / Std / NI / NA

Sp. Reading N.A. T/Radio: Insured / Std / NI / NA

Eng/No: 5YP011204

C/No: 5YP011204

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or affected

Brake: Inorder / Jammed / Leaked / Burnt or affected

Modi: Nil / STD / Rim or

Tyre Size: F: 80/90 217

R: 90/80 217

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pirelli

Front _____ Rear _____

R/Bal. 2 mm R/Bal. 2 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 10/07/2020 D.O.A. 27/08/2020

Survey held at SG 98 AMK

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Front 7 4/8 Panel 9 o/s Panel.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>AXA. SKE 69345</u>
	<u>MV 7K</u>
	<u>LTA 2.8K</u>
	<u>HL 4.2K</u>

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.B.I: (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

> [Back to OneMotoring](#)

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.

FBD8818K

Make / Model

YAMAHA / T135

Vehicle Type :

P00 - Passenger Motorcycle/Autocycle/Moped

Vehicle Attachment 1 :

No Attachment

Vehicle Scheme :

Normal

Chassis No. :

5YP011204

Propellant :

Petrol

Engine No. :

5YP011204

Motor No. :

-

Engine Capacity :

135 cc

Power Rating :

-

Maximum Power Output :

-

Maximum Laden Weight :

-

Unladen Weight :

101 kg

Year Of Manufacture :

2009

Original Registration Date :

09 Sep 2009

Lifespan Expiry Date :

-

COE Category :

D - Motorcycle

PQP Paid :

\$3,214.00

COE Expiry Date :

31 Aug 2029

Road Tax Expiry Date :

08 Sep 2020

PARF Eligibility Expiry Date :

-

Inspection Due Date :

08 Sep 2020

Intended Transfer Date :

26 Aug 2020

CO2 Emission :

-

CEV/VES Rebate Utilised Amount :

-

CO Emission :

-

HC Emission :

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 27 August 2020

To : LKK

Attn : Bryan

By Fax: 6256-4315

Tel: 97237799

VEHICLE NO : FBD 8818K

Yamaha LC 135

ACCIDENT DATE: 10 July 2020

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>	
1 Front Mudguard <i>broken</i>	1	185.00	✓
2 Front Rim <i>broken</i>	1	250.00	✓
3 Brake Disc <i>bst</i>	1	200.00	✓
4 Brake Pump <i>HH</i>	1	250.00	X
5 Fork Tube <i>bst</i>	1 set	350.00	✓
6 Fork Underbracket <i>bst</i>	1	190.00	✓
7 Fork Oil Seal <i>Hec</i>	1	125.00	✓
8 Radiator <i>bst</i>	1	490.00	✓
9 Handle Bar <i>bst</i>	1	125.00	✓
10 Handle Bar Bracket <i>bst</i>	1	155.00	✓
11 Head Lamp <i>broken</i>	1	320.00	✓
12 Head Lamp Cover <i>broken</i>	1	190.00	✓
13 Front Signal Lamp <i>broken</i>	2	150.00	✓
14 Meter Cover <i>broken</i>	1	120.00	✓
15 Front Panel Centre <i>broken</i>	1	190.00	✓
16 Front Side Panel L/RH <i>broken</i>	2	290.00	✓
17 Inner Leg Shield <i>broken</i>	1	135.00	✓
18 Side Panel Inner Holder <i>broken</i>	2	200.00	✓
19 Ignition Switch <i>HH</i>	1	180.00	X
20 Mirror <i>broken</i>	1 set	120.00	✓
21 Centre Garnish Cover <i>broken</i>	1	165.00	✓
22 Centre - V Panel <i>broken</i>	2	160.00	✓
23 Rear Tail Panel LH/RH <i>Cut</i>	2	270.00	✓
24 Exhaust Pipe <i>bst</i>	1	250.00	✓
25 Exhaust Guard <i>HH</i>	1	190.00	X
26 Engine Cover RH <i>HH</i>	1	220.00	X
27 Footrest <i>SVL</i>	1	65.00	X
28 Rear Tail Lamp <i>HH</i>	1	165.00	X
29 Rear Mudguard <i>HH</i>	1	185.00	X

Sub-Total	5,885.00
Less 10%	588.50
Sub-Total	5,296.50

VEHICLE NO : FBD 8818K

Yamaha LC 135

Nett Items

1	Rear number plate <i>Front</i>	15.00	✓
2	Rear box <i>Cnt</i>	180.00	✓
3	Towing fee <i>NH</i>	50.00	X
4	Remove & replace parts, align & etc	350.00	200/-
5	Remove & replace fork assy, rim, brake pump & disc, supply brake oil, etc	200.00	150/-
6	Re-connect harness wiring	120.00	20/-
7	Supply body set decal sticker	120.00	80/-
8	Align body frame	280.00	150/-

Special Nett Items

- 1 Meter Assy *broken*

650.00 ✓

~~280.00~~

Sub-Total

1,595.00

Nett Total

6,891.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.

Thank you

S9 MOTOR TRADING PTE LTD

LG

Repair Lmk.

27/08/2020 @ 1000hrs

Not Available

Assume 5 days.

[Signature]
LKK Auto

*2/12/2020.
Re-inspected
done by LKK-Bryane
LH-Q*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: