

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20009028/T1GA3Q2**Date:** 17/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100510505
Claimant Vehicle No :	SHC3879B	Insured Vehicle No :	SLQ2509E
Date of Loss:	22/08/2020	Nature of Claim:	TP
		Claim No:	4628580490SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC3879B		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2C27058
Reg. Date:	31/05/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU303081248
Colour:	Blue	Odometer:	183613 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	938.70	774.90	163.80	17.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	720.00	550.00	170.00	23.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,658.70	1,324.90	333.80	20.12
+ GST 7.00/7.00% (S\$)	116.11	92.74	23.37	20.13
Nett Amount (S\$)	1,774.81	1,417.64	357.17	20.12
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$126.47/day) (S\$)		379.41		
Nett Liability (S\$)		1,947.05		

INSPECTION

Date of Assignment:	24/08/2020	
Date Inspected:	24/08/2020	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	458.60 FL	*458.60 FL
2	1		*REAR BUMPER CENTER -BLACK	Deformed	552.60 FL	*552.60 FL
3	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*REAR BUMPER TOW COVER	Not Necessary	82.70 FL	*- FL
5	1		*REVERSE SENSOR	Not Necessary	135.70 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$)	1,251.60 1,033.20
					- List Item Discount on L Items 25.00/25.00% (\$)	312.90 258.30
					Total Parts (\$)	938.70 774.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	350.00	320.00
2	SPRAYPAINT CHARGE	New	250.00	200.00
3	R/I REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (\$\$)			720.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >