

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20009033/UVF3E2

**Date:** 08/09/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00072632000	
Claimant Vehicle No :	FBQ5728M	Insured Vehicle No :	SKB7827U	
Date of Loss:	15/08/2020	Nature of Claim:	TP	Claim No: SNM20D203048C02/TOHHS

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ5728M		
Make & Model:	YAMAHA GDR155A (AEROX), 155cc	Engine No:	G3J8E0093503
Reg. Date:	05/11/2019 (Man. Year: 2019)	Chassis No:	MH3SG4640KJ051088
Colour:	Black	Odometer:	32724 km
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	100/80-14	Rear Tyre Size:	120/70 R14
Front Left Side:	Maxxis 7 mm	Rear Left Side:	Maxxis 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,255.70	1,112.50	4,143.20	78.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	960.00	285.00	675.00	70.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,215.70</b>	<b>1,397.50</b>	<b>4,818.20</b>	<b>77.52</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,215.70</b>	<b>1,100.00</b>	<b>5,115.70</b>	<b>82.30</b>

### INSPECTION

Date of Assignment:	26/08/2020	
Date Inspected:	27/08/2020 Inspected At:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	4.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 08 Sep 2020)	
<b>Parts:</b>	N/A	YAMAHA GDR155A (AEROX) 155cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBQ5728M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK ASSY	Repair	980.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Not Necessary	190.00 FL	*- FL
3	1		*FRONT SPORT RIM	Not Necessary	550.00 FL	*- FL
4	1		*FRONT BRAKE DISC	Not Necessary	180.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Not Necessary	52.00 FL	*- FL
6	1		*HEAD LAMP	Cracked	550.00 FL	*550.00 FL
7	1		*HANDLE-BAR	Not Necessary	135.00 FL	*- FL
8	1		*FRONT SIGNALS	N/S Cracked	150.00 FL	*75.00 FL
9	1		*FOOTSTEP PANEL (CUT)	Not Consistent With The Impact	255.00 FL	*- FL
10	1		*EXHAUST ASSY	Not Necessary	680.00 FL	*- FL
11	1		*EXHAUST PROTECTOR (SCRATCHED)	Not Consistent With The Impact	48.00 FL	*- FL
12	1		*MAIN STAND (SCRATCHED)	Not Consistent With The Impact	145.00 FL	*- FL
13	1		*REAR MUDGUARD (CRACKED)	Not Consistent With The Impact	148.00 FL	*- FL
14	1		*FRONT FAIRING	Cracked	1,450.00 FL	*600.00 FL
15	1		*SET NUMBER PLATE	Front Missing	28.00 FS	*10.00 FS
16	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
17	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
18	1		*SET STEERING CONE	Not Necessary	120.00 FS	*- FS
19	1		*AEROX EMBLEM	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,807.00</b>	<b>1,235.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	551.30	122.50
<b>Total Parts (\$\$)</b>	<b>5,255.70</b>	<b>1,112.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	50.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO REPAIR BODY FRAME	New	380.00	0.00
4	TO PROVIDE LABOUR	New	450.00	250.00
<b>Gross Labour Cost (S\$)</b>			<b>960.00</b>	<b>285.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >