

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20009034/AVF3E2

Date: 10/02/2021

REFERENCE

Insured/Claimant: ISA RAFIQ MOHAMED S/O ABDUL KHADER

Policy No: 2100508434

Date of Loss: 20/08/2020

Nature of Claim: OD Claim No: 3255147590SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN1854E**

Make & Model: AUDI A6, 1.8 TFSI S-tronic (A)

Engine No: CYG017724

Reg. Date: 25/04/2017 (Man. Year: 2016)

Chassis No: WAUZZZ4G4HN061761

Colour: Black

Odometer: 60680 km

Engine Capacity: 1798 cc

Market Value/New Car Price: S\$105,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,513.00	2,746.16	4,766.84	63.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,632.00	1,602.00	4,030.00	71.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,145.00	4,348.16	8,796.84	66.92
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	12,345.00	3,548.16	8,796.84	71.26
+ GST 7.00/7.00% (S\$)	864.15	248.37	615.78	71.26
Nett Amount (S\$)	13,209.15	3,796.53	9,412.62	71.26

INSPECTION

Date of Assignment: 26/08/2020

Date Inspected: 26/08/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,897.00 FS	*2,317.60 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	270.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Deformed	474.00 FS	*378.80 FS
4	1		*REAR BUMPER SECURING STRIP	Not Necessary	220.00 FS	*- FS
5	1		*REAR BUMPER CLOSING ELEMENT - LH	Not Necessary	80.00 FS	*- FS
6	1		*EXHAUST TAIL PIPE TRIM	Not Necessary	561.00 FS	*- FS
7	1		*REAR SILENCER	Not Necessary	1,276.00 FS	*- FS
8	1		*REAR SILENCER DUAL CLIP	Not Necessary	57.00 FS	*- FS
9	1		*REAR SILENCER BRACKET	Not Necessary	57.00 FS	*- FS
10	1		*REAR BUMPER CARRIER	Not Necessary	960.00 FS	*- FS
11	2		*REAR BUMPER CARRIER SEAL - LH / RH	Not Necessary	28.00 FS	*- FS
12	1		*REAR BUMPER GUIDE PROFILE - LH	Not Necessary	66.00 FS	*- FS
13	1		*REAR BUMPER GUIDE SECTION - CENTRE	Not Necessary	105.00 FS	*- FS
14	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	53.00 FS	*- FS
15	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	33.00 FS	*- FS
16	1		*REAR BUMPER HOLDING STRAP - LH	Not Necessary	63.00 FS	*- FS
17	1		*REAR BUMPER CONNECTING PIECE	Not Necessary	13.00 FS	*- FS
18	2		*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
19	1		*SUNDRIES	Necessary	300.00 FS	*49.76 FS
					Total Parts (\$\$)	7,513.00 2,746.16

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
3	TO RESPRAY REAR BUMPER, LHS REAR FENDER AND LHS REAR DOOR	New	3,000.00	550.00
4	TO REMOVE AND RENEW LHS REAR EXHAUST SILENCER AND ALIGN TO POSITION	New	480.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,632.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >