Adjuster Report Page 1 of 4

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009041/R1ES3Q2

**Date:** 30/11/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700043777

Claimant
Vehicle No: FBQ7803R

FBQ7803R

Insured Vehicle No: SBC111Z

Date of Loss: 24/08/2020 Nature of Claim: TP Claim No: 3311061711SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FBQ7803R

Make & Model: YAMAHA JUPITER 115 Z1, 114cc Engine No: E3R5E0245062

 Reg. Date:
 13/12/2019 (Man. Year: 2019)
 Chassis No:
 MH3UE1120KJ233276

 Colour:
 Blue
 Odometer:
 17957 km

Colour: Blue Engine Capacity: 114 cc

Engine Capacity:
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 70/90-17 Rear Tyre Size: 80/90-17 Front Left Side: Michelin 3 mm Rear Left Side: Michelin 3 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,549.60	804.70	3,744.90	82.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	280.00	1,320.00	82.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,149.60	1,084.70	5,064.90	82.36
Approved Total (Overridden) (S\$)		850.00		
Nett Amount (S\$)	6,149.60	850.00	5,299.60	86.18
Global Sum Settlement (S\$)		0.00		

**INSPECTION** 

Date of Assignment: 26/08/2020

Date Inspected: 27/08/2020 Inspected At: Karz Work Solutions (HQ)

53 Ubi Avenue 1 #02-24, Paya Ubi

Industrial Park Singapore 408934

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	2		*FRONT FORK TUBE	Bent	640.00 FL	*500.00 FL	
2	1		*HANDLE BAR	Not Necessary	350.00 FL	*- FL	
3	2		*BALANCER	Not Necessary	180.00 FL	*- FL	
4	2		*SIDE MIRROR	Not Necessary	150.00 FL	*- FL	
5	1		*FRONT FOOTREST	Not Necessary	75.00 FL	*- FL	
6	1		*FRONT FOOTREST BRACKET	Bent	96.00 FL	*85.00 FL	
7	1		*FRONT FOOTREST BRACKET STOPPER	Serviceable	110.00 FL	*- FL	
8	1		*FRONT FENDER	Not Necessary	250.00 FL	*- FL	
9	1		*FRONT FENDER GARNISH	Not Necessary	105.00 FL	*- FL	
10	1		*FRONT HEADLAMP	Not Necessary	500.00 FL	*- FL	
11	1		*STEERING HEADCROWN	Not Necessary	480.00 FL	*- FL	
12	1		*BRAKE LEVER	Bent	68.00 FL	*68.00 FL	
13	1		*FRONT RH FAIRING	Repair	250.00 FL	*- FL	
14	1		*REAR EXHAUST	Serviceable	800.00 FL	*- FL	
15	1		*EXHAUST CHROME COVER	Scratched	210.00 FL	*130.00 FL	
16	1		*MAIN STAND	Serviceable	60.00 FL	*- FL	
17	1		*SIDE STAND	Serviceable	60.00 FL	*- FL	
18	1		*FRONT WHEEL RIM	Not Necessary	400.00FS	*- FS	
19	1		*SET GEAR SHIT SHAFT OIL SEAL	Not Necessary	24.00 FS	*- FS	
20	2		*FORK OIL SEAL	Necessary	120.00 FS	*60.00 FS	
21	1		*BOT FORK OIL	Necessary	60.00FS	*40.00 FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
				Sub Total (S\$)	4,988.00	883.00	
- List Item Discount on L Items 10.00/10.00% (S\$) 438.40 78.30						78.30	
				Total Parts (S\$)	4,549.60	804.70	
Report was unsubmitted during this print-out.							
Ь——							

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REPLACE,REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTING SYSTEM	New	350.00	50.00
2	TO KNOCK,STRAIGHTEN CHASSIS AND BODY BALANCING	New	500.00	0.00
3	TO REMOVE/REFIT, REPLACE FRONT FORK TUDES	New	250.00	150.00
4	SPRAY PAINTING	New	500.00	80.00
	Gross Labour Cost (S\$)		1,600.00	280.00
		,		

< END OF ESTIMATES >

Report was unsubmitted during this print-out.