

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBA 1854S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	BENT	160.00	160.00
1	SET HANDLE GRIP	USABLE	60.00	-
2	SET MIRROR ASSY @\$65.00	GRAZED	130.00	100.00
1	BRAKE LEVER	BENT / CUT	43.00	43.00
1	SIDE FAIRING RH	CUT	348.50	280.00
2	FRONT SIGNAL @\$85.00	O/S CRACKED	170.00	85.00
2	FRONT FOOTREST @\$75.00	O/S BENT	150.00	75.00
2	FRONT FOOTREST BRACKET @\$195.00	SERVICEABLE	390.00	-
1	BRAKE PEDAL	USABLE	68.00	-
1	LOWER COWLING (BELLY PAN)	SERVICEABLE	105.00	-
1	EXHAUST MUFFLER (YOSHIMURA)	DENTED	1,800.00	1,500.00
	LESS 10% DISCOUNT		-342.45	-224.30
			3,082.05	2,018.70
	<u>SPECIAL NETT ITEMS</u>			
1	ENGINE GUARD (SN)	CUT	350.00	200.00
1	EXHAUST MUFFLER GASKET (SN)	NECESSARY	35.00	25.00
			385.00	225.00
	<u>LABOUR</u>			
	SPRAY PAINTING ON FUEL & FRONT FENDER.		550.00	300.00
	TO REPAIR AND RENEW DAMAGED PARTS.		500.00	300.00
			1,050.00	600.00
	GRAND TOTAL		4,517.05	2,843.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,250.00

Report Ref No. CS3/III20004541/Eyf3e2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.