

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20009050/ATF3E2

Date: 20/04/2021

REFERENCE

Insured/Claimant: CHONG YU SHAN, AUDREY(ZHANG YUSHAN,AUDREY) Policy No: 1900261253

Date of Loss: 21/08/2020

Nature of Claim: OD

Claim No: 5878308276SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFW3104Y	Engine No:	CYR100220
Make & Model:	AUDI Q7, 2.0 TFSI QU (A)	Chassis No:	WAUZZZ4M0KD046435
Reg. Date:	27/12/2019 (Man. Year: 2019)	Odometer:	11008 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$240,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55 R19	Rear Tyre Size:	255/55 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	45,517.40	28,627.52	16,889.88	37.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	24,212.00	13,372.00	10,840.00	44.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	69,729.40	41,999.52	27,729.88	39.77
+ GST 7.00/7.00% (S\$)	4,881.06	2,939.97	1,941.09	39.77
Nett Amount (S\$)	74,610.46	44,939.49	29,670.97	39.77

INSPECTION

Date of Assignment: 27/08/2020

Date Inspected: 27/08/2020 Inspected At:

24 BENOI SECTOR

Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 15.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	2,434.00 FS	*1,947.20 FS
2	1	*FRONT BUMPER FIXING PARTS	Damaged	442.00 FS	*353.60 FS
3	1	*FRONT BUMPER AIR GUIDE - LH	Distorted	66.00 FS	*52.40 FS
4	1	*FRONT BUMPER END CAP - LH	Distorted	35.00 FS	*27.84 FS
5	1	*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Distorted	273.00 FS	*218.40 FS
6	1	*FRONT BUMPER GRILLE - LOWER CENTRE	Cracked	203.00 FS	*162.40 FS
7	1	*FRONT UNDDERRUN BAR	Deformed	797.00 FS	*637.60 FS
8	1	*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Distorted	209.00 FS	*166.00 FS
9	1	*FRONT BUMPER SPOILER - LH	Distorted	43.00 FS	*34.24 FS
10	1	*RADIATOR GRILLE	Cracked	2,445.00 FS	*1,956.00 FS
11	1	*RADIATOR GRILLE COVER	Not Necessary	72.00 FS	*- FS
12	1	*FRONT BUMPER COVER	Deformed	61.00 FS	*48.72 FS
13	1	*FRONT AIR GUIDE GRILLE - LH	Distorted	294.00 FS	*234.80 FS
14	1	*FRONT BUMPER END CAP - LH	Distorted	33.00 FS	*26.08 FS
15	1	*SPRING CLIP - LH	Necessary	4.00 FS	*2.56 FS
16	1	*FRONT BUMPER SPOILER - LH	Distorted	57.00 FS	*44.96 FS
17	1	*FRONT REINFORCEMENT BAR	Bent	858.00 FS	*686.00 FS
18	1	*FRONT FOAM FILLER PIECE	Cracked	170.00 FS	*135.60 FS
19	1	*FRONT BUMPER GUIDE SECTION - LH	Damaged	44.00 FS	*34.48 FS
20	1	*FRONT BUMPER SUPPORT - LH / RH	N/S Damaged	72.00 FS	*28.24 FS
21	1	*FRONT REINFORCEMENT BEAM COVER	Cracked	129.00 FS	*103.20 FS
22	1	*SIGN CAUTION STICKER	Necessary	14.00 FS	*10.80 FS
23	1	*FRONT SENSOR - INNER / OUTER (2PCS)	Damaged (1Pc Only)	386.40 FS	*193.20 FS
24	4	*FRONT SENSOR SEAL RING	Necessary	14.00 FS	*10.88 FS
25	1	*SET FRONT BUMPER WIRING	Not Necessary	625.00 FS	*- FS
26	1	*FRONT FANFARE - LOW TONE	Cracked	223.00 FS	*178.40 FS
27	1	*FRONT FLAT CONNECTOR HOUSING	Necessary	20.00 FS	*15.76 FS
28	1	*FRONT FENDER - LH	Repair	1,602.00 FS	*- FS
29	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
30	1	*FRONT FENDER BRACE	Not Necessary	100.00 FS	*- FS
31	1	*FRONT WHEEL HOUSING LINER - LH	Crumpled	237.00 FS	*189.20 FS
32	1	*HEADLIGHT MOUNTING - LH	Cracked	117.00 FS	*93.60 FS
33	1	*LED HEADLIGHT	Cut	9,813.00 FS	*7,850.40 FS
34	1	*LED HEADLIGHT COVER	Necessary	101.00 FS	*80.80 FS
35	1	*LED HEADLIGHT LIFT CYLINDER - LH	Cracked	196.00 FS	*156.80 FS
36	1	*LED HEADLIGHT HOSE	Not Necessary	96.00 FS	*- FS
37	1	*BONNET LID LOCK	Damaged	207.00 FS	*165.20 FS
38	1	*FRONT LOCK CARRIER	Cracked	1,190.00 FS	*952.00 FS
39	1	*A/C CONDENSER	Not Necessary	920.00 FS	*- FS
40	1	*REFRIGERANT LINE	Bent	211.00 FS	*168.40 FS
41	1	*REFRIGERANT LINE	Bent	241.00 FS	*192.80 FS
42	1	*REFRIGERANT PIPE	Not Necessary	510.00 FS	*- FS
43	1	*REFRIGERANT LINE	Not Necessary	211.00 FS	*- FS
44	1	*RADIATOR	Not Necessary	927.00 FS	*- FS
45	1	*RADIATOR PRESSURE HOSE - LH	Cut	260.00 FS	*207.60 FS
46	1	*ADDITIONAL RADIATOR	Dented	837.00 FS	*669.20 FS
47	4	*RADIATOR COOLANT	Necessary	177.00 FS	*141.44 FS
48	1	*ADDITIONAL RADIATOR	Not Necessary	741.00 FS	*- FS
49	1	*RADIATOR AIR GUIDE - LEFT OUTER	Distorted	45.00 FS	*35.92 FS
50	1	*ADDITIONAL RADIATOR BRACKET	Not Necessary	124.00 FS	*- FS
51	1	*ADDITIONAL RADIATOR BRACKET - LH REAR	Not Necessary	25.00 FS	*- FS
52	1	*RADIATOR COOLANT HOSE - LOWER	Not Necessary	230.00 FS	*- FS
53	2	*RADIATOR TWIN FAN CONTROL UNIT - LH / RH	Not Necessary	3,018.00 FS	*- FS
54	1	*RADIATOR AIR GUIDE - LH	Cracked	28.00 FS	*22.32 FS
55	1	*RADIATOR AIR GUIDE - LOWER	Cracked	42.00 FS	*32.88 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
56	1	*RADIATOR AIR GUIDE - UPPER	Cracked	42.00 FS	*32.88 FS
57	2	*FRONT WHEEL COVER - LH / RH	Necessary	1,138.00 FS	*909.60 FS
58	1	*FRONT UNDERCARRIAGE COVER	Crumpled	637.00 FS	*509.20 FS
59	1	*SUNDRIES	Necessary	400.00 FS	*102.08 FS
60	1	*HEADLIGHT LED RHS	Cracked	9,813.00 FS	*7,850.40 FS
61	1	*INTAKE AIR DUCT TOP	Deformed	130.00 FS	*104.00 FS
62	1	*BONNET STRIKER LHS	Bent	112.00 FS	*89.60 FS
63	1	*BONNET BOWDEN CABLE CENTRE	Damaged	57.00 FS	*45.52 FS
64	1	*FRONT BUMPER LOWER SPOILER LHS	Distorted	209.00 FS	*166.80 FS
65	1	*ADAPTER CABLE LOOM CRASH SENSOR FOR AIRBAG	Snapped	51.00 FS	*40.24 FS
66	1	*FRONT BUMPER GUIDE SECTION RHS	Cracked	44.00 FS	*34.48 FS
67	1	*RADIATOR AIR GUIDE RHS	Cracked	28.00 FS	*22.32 FS
68	1	*TEMPERATURE SENSOR BRACKET	Necessary	5.00 FS	*3.28 FS
69	1	*HEADLIGHT MOUNTING RHS	Cracked	117.00 FS	*93.60 FS
70	1	*ENGINE MOUNTING LHS	Cracked	370.00 FS	*295.60 FS
71	1	*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 45,517.40 28,627.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	450.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO REMOVE AND RENEW AIRCOND REFRIGERANT PIPE. (FROM AIRCON COMPRESSOR AND AIRCON CONDENSER TO CUT OFF POINT)	New	300.00	300.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS & RHS FRONT FENDER, LHS HEADLIGHT, BONNET. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,400.00	2,100.00
6	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER LHS, LHS & RHS FRONT FENDER, BOTH FRONT WHEEL ARC TRIMS AND BONNET	New	5,400.00	3,000.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	450.00	250.00
9	TO CARRY OUT WHEEL ALIGNMENT TEST	New	240.00	0.00
10	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER	New	800.00	800.00
11	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE RENEWAL OF ENGINE MOUNTING	New	2,800.00	0.00
12	TO CARRY OUT REPAIRING OF FRONT CHASSIS FRAME LHS ON CAR-LINER	New	2,700.00	1,000.00
13	TO SETUP THE CAR ON CAR-O-LINER	New	2,400.00	2,400.00
14	TO DISLODGE AND REINSTALL ENGINE ASSY. TO REMOVE AND REINSTALL AIRCON COMPRESSOR. TO DISLODGE AND REINSTALL FRONT SUBFRAME TO FACILITATE RENEWAL OF ENGINE MOUNTING LHS	New	1,200.00	1,200.00
Gross Labour Cost (\$\$)			24,212.00	13,372.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >