

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20009054/R1QF3E2

Date: 25/11/2020

REFERENCE

Insured/Claimant:	SRIVATS HARIHARAN	Policy No:	190012167	
Date of Loss:	25/08/2020	Nature of Claim:	OD	Claim No: 1209903681SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM8993J		
Make & Model:	AUDI A3, 999cc SEDAN TFSI (A)	Engine No:	CHZC27822
Reg. Date:	18/07/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ8V9K1025247
Colour:	Grey	Odometer:	18198 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$99,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,080.84	8,048.72	4,032.12	33.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,472.00	2,572.00	1,900.00	42.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,552.84	10,620.72	5,932.12	35.84
- Excess (\$\$)	300.00	300.00	0.00	0.00
(\$\$)	16,252.84	10,320.72	5,932.12	36.50
+ GST 7.00/7.00% (\$\$)	1,137.70	722.45	415.25	36.50
Nett Amount (\$\$)	17,390.54	11,043.17	6,347.37	36.50

INSPECTION

Date of Assignment:	27/08/2020	
Date Inspected:	28/08/2020	Inspected At: 281 Alexandra Road
		Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Serviceable	185.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - LH	Serviceable	38.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	159.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	530.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	293.00 FS	*- FS
7	1		*FRONT BUMPER COVER TRIM - LH	Not Necessary	161.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
9	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	189.00 FS	*150.80 FS
10	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
11	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
12	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	186.00 FS	*- FS
13	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Bent	715.00 FS	*571.60 FS
14	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	187.00 FS	*149.60 FS
15	1		*FOAM FILLER PIECE COVER	Serviceable	121.00 FS	*- FS
16	1		*LED HEADLIGHT - LH	Cracked	5,455.00 FS	*4,364.00 FS
17	1		*LIFT CYLINDER - LH	Not Necessary	141.00 FS	*- FS
18	1		*RADIATOR AIR GUIDE - LH	Not Necessary	24.00 FS	*- FS
19	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
20	1		*BONNET EDGE PROTECTION	Necessary	21.84 FS	*21.84 FS
21	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 12,080.84 8,048.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	280.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
4	TO RESPRAY FRONT BUMPER	New	900.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO REPAIR LHS FRONT FENDER	New	700.00	250.00
7	TO RESPRAY LHS FRONT FENDER	New	1,000.00	550.00
Gross Labour Cost (\$\$)			4,472.00	2,572.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >