

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/TMI20009055/T1QF3E2

**Date:** 21/09/2020

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MK000836

**Claimant Vehicle No :** SHA5637E

**Insured Vehicle No :** SLT4568E

Date of Loss: 25/08/2020

Nature of Claim: TP

Claim No: M2004144

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA5637E**

Make & Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4FDEU411155

Reg. Date: 14/04/2016 (Man. Year: 2015)

Chassis No: KMHLB41UMGU087170

Colour: Blue

Odometer: 631987 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes

Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No

Pre-accident Condition: Good

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60R16

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,826.82	1,141.86	684.96	37.49
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	670.00	510.00	160.00	23.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,507.82</b>	<b>1,662.86</b>	<b>844.96</b>	<b>33.69</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,350.00</b>		
<b>(S\$)</b>	2,507.82	1,350.00	1,157.82	46.17
<b>+ GST 7.00/7.00% (S\$)</b>	175.55	94.50	81.05	46.17
<b>Nett Amount (S\$)</b>	<b>2,683.37</b>	<b>1,444.50</b>	<b>1,238.87</b>	<b>46.17</b>

### INSPECTION

Date of Assignment: 27/08/2020 Present Location:

ComfortDelGro Engineering Pte Ltd  
(Loyang)

Date Inspected: 26/08/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 2.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2020)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHA5637E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Deformed	1,106.00 FL	-	*1,106.00 FL
2	1		*REAR BUMPER UNDER COVER	Repair	228.00 FL	-	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	428.40 FL	-	*- FL
4	1		*REAR BUMPER REINFORCEMENT STAY LH	Not Necessary	80.30 FL	-	*- FL
5	1		*REAR BUMPER SPONGE	Not Necessary	119.50 FL	-	*- FL
6	1		*REAR BUMPER SIDE BRACKET LH	Necessary	35.20 FL	-	*35.20 FL
7	1		*REAR BUMPER REFLECTOR LH	Cut	32.00 FL	-	*32.00 FL
8	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
9	1		*REVERSE SENSOR	Not Working	135.70 F	-	*135.70 F
10	1		*REAR BUMPER MAT	Necessary	50.00 F	-	*50.00 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,237.10</b>	<b>1,380.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	410.28	239.04
<b>Total Parts (\$\$)</b>	<b>1,826.82</b>	<b>1,141.86</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	300.00	280.00
2	SPRAY PAINTING	New	250.00	200.00
3	R/I REVERSE SENSOR	New	120.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>670.00</b>	<b>510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >