

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TM120009057/T1SF3E2

Date: 06/10/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: ML000127

Claimant Vehicle No : SHC7623X

Insured Vehicle No : SLK6922A

Date of Loss: 25/08/2020

Nature of Claim: TP

Claim No: M2004153

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC7623X**

Make & Model: HYUNDAI AE IONIQ HEV DCT, 1.6 (A)

Engine No: G4LEKU364112

Reg. Date: 14/11/2019 (Man. Year: 2019)

Chassis No: KMHC851CVLU178616

Colour: Yellow

Odometer: 95486 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Excellent

Steering (Serviceable): Yes

Footbrake (Serviceable): Yes

Yes

Handbrake (Serviceable): Yes

Engine Modification: No

Pre-accident Condition: Good

Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,330.64	428.60	14,902.04	97.20
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,810.00	550.00	2,260.00	80.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,151.64	989.60	17,162.04	94.55
+ GST 7.00/7.00% (S\$)	1,270.61	69.27	1,201.34	94.55
Nett Amount (S\$)	19,422.25	1,058.87	18,363.38	94.55

INSPECTION

Date of Assignment: 27/08/2020 Present Location:

ComfortDelGro Engineering Pte Ltd
(Loyang)

Date Inspected: 26/08/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 06 Oct 2020)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC7623X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BONNET ASSY	Repair	2,253.80 FL	-	*- FL
2	1		*RADIATOR GRILLE	Not Necessary	1,409.10 FL	-	*- FL
3	1		*RADIATOR GRILLE UPPER GARNISH	Not Necessary	188.00 FL	-	*- FL
4	1		*FRONT BUMPER COVER	Not Necessary	418.30 FL	-	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,075.10 FL	-	*- FL
6	1		*FRONT BUMPER SPONGE/ABSORBER	Not Necessary	86.90 FL	-	*- FL
7	2		*FRONT BUMPER GRILLE LH/RH	Not Necessary	186.90 FL	-	*- FL
8	1		*FRONT BUMPER TOW COVER	Not Necessary	29.00 FL	-	*- FL
9	1		*FRONT BUMPER CENTRE MOULDING	Not Necessary	187.20 FL	-	*- FL
10	1		*FRONT BUMPER LOWER LIP	Not Necessary	85.10 FL	-	*- FL
11	2		*FRONT BUMPER BRACKET LH/RH	Not Necessary	56.00 FL	-	*- FL
12	1		*FRONT NUMBER PLATE GARNISH	Not Necessary	188.00 FL	-	*- FL
13	2		*FRONT BUMPER TOP BRACKET LH/RH	Not Necessary	70.00 FL	-	*- FL
14	1		*HEADLAMP SUPPORT PANEL	Not Necessary	949.30 FL	-	*- FL
15	1		*HEADLAMP ASSY LH/RH	Not Necessary	1,993.65 FL	-	*- FL
16	2		*DAY LIGHT LH/RH	Not Necessary	1,285.00 FL	-	*- FL
17	1		*RADIATOR	Not Necessary	510.50 FL	-	*- FL
18	1		*RADIATOR BLOWER MOTOR ASSY	Not Necessary	576.00 FL	-	*- FL
19	1		*RADIATOR FAN	Not Necessary	375.00 FL	-	*- FL
20	1		*RADIATOR TANK RESERVOIR	Not Necessary	110.10 FL	-	*- FL
21	2		*RADIATOR AIR GUARD LH/RH	Not Necessary	52.00 FL	-	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
22	1		*RADIATOR INVERTER	Not Necessary	884.80 FL	-	*- FL
23	2		*FLAP ASSY ACTIVE LH/RH	Not Necessary	712.00 FL	-	*- FL
24	2		*ACTUATOR ACTIVE LH/RH	Not Necessary	514.20 FL	-	*- FL
25	1		*AIR CON CONDENSER	Not Necessary	663.60 FL	-	*- FL
26	1		*AIR CON DISCHARGER HOSE	Not Necessary	148.50 FL	-	*- FL
27	1		*AIR CON SUNCTION /LIQUID	Not Necessary	679.60 FL	-	*- FL
28	1		*FRONT FENDER RH	Not Necessary	490.70 FL	-	*- FL
29	1		*FRONT EMBLEM BD FENDER RH	Not Necessary	26.60 FL	-	*- FL
30	1		*FRONT PILLAR DELTA GARNISH	Not Necessary	42.80 FL	-	*- FL
31	1		*FRONT SMART RADAR SENSOR	Not Necessary	812.50 FL	-	*- FL
32	1		*REAR BUMPER	Repair	459.40 FL	-	*- FL
33	1		*REAR BUMPER CENTRE MOULDING	Cracked	451.25 FL	-	*451.25 FL
34	1		*REAR BUMPER REINFORCEMENT	Not Necessary	294.80 FL	-	*- FL
35	2		*REAR BUMPER REINFORCEMENT STAY LH/RH	Not Necessary	276.20 FL	-	*- FL
36	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
37	2		*REAR BUMPER BRACKET LH/RH	Not Necessary	111.60 FL	-	*- FL
38	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	-	*- FL
39	1		*REAR NUMBER PLATE W/HOLDER	Cracked	50.00 FL	-	*50.00 FS
40	1		*FRONT NUMBER PLATE W/HOLDER	Not Necessary	50.00 FL	-	*- FL
41	1		*REAR BUMPER MAT	Not Necessary	50.00 FL	-	*- FL
Supplementary #1							
42	1		*COVER RADIATOR GRANISH TOP	Not Necessary	48.30 FL	-	*- FL
43	1		*ANTENNA ASSY SMART	Not Necessary	40.50 FL	-	*- FL
44	1		*REAR BUMPER MOULDING UNDER COVER	Not Necessary	47.50 FL	-	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	19,163.30	523.25
- List Item Discount on L Items 20.00/20.00% (\$)	3,832.66	94.65
Total Parts (\$)	15,330.64	428.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING FRONT /REAR	New	1,280.00	320.00
2	SPRAY PAINTING FRONT/ REAR	New	700.00	200.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	120.00	0.00
5	REMOVE/ REFIX RADIATOR / COOLING SYSTEM	New	90.00	0.00
6	REMOVE/ REFIX AIR CON SYSTEM / CHARGE IN GAS	New	120.00	0.00
7	DIAGNOSE & RESET ERROR FAULT CODE	New	400.00	0.00
Gross Labour Cost (\$\$)			2,810.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >