

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Sep 2020 13:21 Edit Reg		27 Aug 2020 00:00 Edit Adj Rpt	S\$2,400.00 Edit Estimates	S\$2,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured: 0 , Co. Reg. No.: 0									
Main Claimant: -									
Vehicle Reg. No.: SGB7551L		Date of Loss: 25/08/2020 00:00 - :59 [138 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): GBK1748M		Policy No. (Claimant):							
		Excess:							
Repairer: People's Vehicle Recovery Service (HQ) Blk 3023A Ubi Rd 1, #01-60, 408717 Ubi - Tel: 67433246									
Handling Insurer: ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/09/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS ☐			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGB7551L
[GBK1748M]
TP
-

Aug 25 2020 12:00AM
[0]
People's Vehicle Recovery Service

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/09/20 13:23	Adjuster Immediate Advice	 Load HTM	
2	23/09/20 13:27	Adjuster Immediate Advice	 Load HTM	

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/09/20 16:07	General View	 Load JPG	☒
2	26/09/20 16:07	General View	 Load JPG	☒
3	26/09/20 16:07	General View	 Load JPG	☒
4	26/09/20 16:07	General View	 Load JPG	☒
5	26/09/20 16:07	General View	 Load JPG	☒
6	26/09/20 16:07	General View	 Load JPG	☒
7	26/09/20 16:07	General View	 Load JPG	☒
8	26/09/20 16:07	General View	 Load JPG	☒
9	26/09/20 16:07	General View	 Load JPG	☒
10	26/09/20 16:07	General View	 Load JPG	☒
11	26/09/20 16:07	General View	 Load JPG	☒
12	26/09/20 16:07	General View	 Load JPG	☒
13	26/09/20 16:07	General View	 Load JPG	☒
14	26/09/20 16:07	General View	 Load JPG	☒
15	26/09/20 16:07	General View	 Load JPG	☒
16	26/09/20 16:07	General View	 Load JPG	☒
17	26/09/20 16:07	General View	 Load JPG	☒
18	26/09/20 16:07	General View	 Load JPG	☒
19	26/09/20 16:07	General View	 Load JPG	☒
20	26/09/20 16:07	General View	 Load JPG	☒
21	26/09/20 16:07	General View	 Load JPG	☒
22	26/09/20 16:07	General View	 Load JPG	☒
23	26/09/20 16:07	General View	 Load JPG	☒
24	26/09/20 16:07	Reinspection Photo	 Load JPG	☒
25	26/09/20 16:07	Reinspection Photo	 Load JPG	☒
26	26/09/20 16:07	Reinspection Photo	 Load JPG	☒
27	26/09/20 16:07	Reinspection Photo	 Load JPG	☒
28	26/09/20 16:07	Reinspection Photo	 Load JPG	☒
29	26/09/20 16:07	Reinspection Photo	 Load JPG	☒
30	26/09/20 16:07	Reinspection Photo	 Load JPG	☒
31	26/09/20 16:07	Reinspection Photo	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG120009061/ATF3S2**Date:** 28/09/2020**REFERENCE**

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SGB7551L	Insured Vehicle No :	GBK1748M
Date of Loss:	25/08/2020	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGB7551L		
Make & Model:	TOYOTA PICNIC, 2.0 W/O ROOF RACK (A)	Engine No:	1AZ5846234
Reg. Date:	09/02/2009 (Man. Year: 2008)	Chassis No:	JTEGH23B400026340
Colour:	Black	Odometer:	202291 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,417.80	2,051.32	366.48	15.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,170.00	950.00	220.00	18.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,587.80	3,001.32	586.48	16.35
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	3,587.80	2,400.00	1,187.80	33.11
+ GST 7.00/7.00% (S\$)	251.15	168.00	83.15	33.11
Nett Amount (S\$)	3,838.95	2,568.00	1,270.95	33.11

INSPECTION

Date of Assignment:	27/08/2020		
Date Inspected:	01/09/2020	Inspected At:	People's Vehicle Recovery Service (HQ) Blk 3023A Ubi Rd 1, #01-60 Singapore 408717
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Sep 2020)

Parts: M1-MPV TOYOTA PICNIC 2.0 W/O ROOF RACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGB7551L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP R/H	Cracked	557.93 FL	*557.93 FL
2	1		*BUMPER FRT	Deformed	553.85 FL	*553.85 FL
3	1		*FENDER R/H FRT	Dented	538.93 FL	*538.93 FL
4	1		*FENDER INNER SHIELD R/H FRT	Not Necessary	291.13 FL	*- FL
5	6		*FENDER INNER SHIELD CLIPS FRT	Not Necessary	34.80 FL	*- FL
6	1		*BUMPER SIDE RETAINER R/H FRT	Necessary	89.39 FL	*89.39 FL
7	1		*WING MIRROR	Damaged	1,157.70 FL	*995.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,223.73	2,735.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	805.93	683.78
Total Parts (\$\$)	2,417.80	2,051.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REPLACE ACCIDENT DAMAGED PARTS.	New	500.00	400.00
2	SPRAY PAINTING ACCIDENT EFFECT PARTS.	New	450.00	400.00
3	COMPUTERIZED WHEEL ALIGNMENT.	New	80.00	80.00
4	CHECK ALL LIGHTING AFTER REPAIR.	New	60.00	30.00
5	UNDERCOAT.	New	80.00	40.00
Gross Labour Cost (\$)			1,170.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >