

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20009062/R1CF3E2
Date: 02/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00041522000
Claimant Vehicle No :	SMG7395Z	Insured Vehicle No :	GBJ5210B
Date of Loss:	25/08/2020	Nature of Claim:	TP
		Claim No:	SNM20D203062/C02/TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG7395Z	Engine No:	CHZA58663
Make & Model:	SKODA OCTAVIA, 999cc TSI AMBITION PLUS (A)	Chassis No:	TMBBP7NE2J0362849
Reg. Date:	28/12/2018 (Man. Year: 2018)	Odometer:	18919 km
Colour:	Blue		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,173.18	6,251.78	4,921.40	44.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,930.00	8,750.00	8,180.00	48.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	28,103.18	15,001.78	13,101.40	46.62
+ GST 7.00/7.00% (S\$)	1,967.22	1,050.12	917.10	46.62
Nett Amount (S\$)	30,070.40	16,051.90	14,018.50	46.62

INSPECTION

Date of Assignment:	27/08/2020		
Date Inspected:	28/08/2020	Inspected At:	Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	9.0 days		

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$7,225.04 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Feb 2021)

Parts: 143 SKODA OCTAVIA 999cc TSI AMBITION PLUS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMG7395Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR (LHR DOOR)	Bent	3,040.00 FS	*3,040.00 FS
2	1		*DOOR SEAL LOWER LH	Necessary	99.40 FS	*99.40 FS
3	1		*LHR DOOR SEAL (SIDE)	Necessary	70.20 FS	*70.20 FS
4	6		*DOOR BOARD CLIP	Necessary	10.20 FS	*10.20 FS
5	1		*SOUND ABSORBER DOOR INSULATOR	Necessary	67.14 FS	*67.14 FS
6	1		*DOOR HANDLE OUTER PRIMED	Repair	172.96 FS	*- FS
7	1		*COVER FOR	* Check	1,240.00 FS	*- FS
8	1		*GUIDE PIEC BUMPER SIDE BRACKET LH	Not Necessary	43.40 FS	*- FS
9	1		*WHEELHOUSE LHR FENDER LINER	* Check	107.00 FS	*- FS
10	1		*SECTIONAL (LHR FENDER)	Buckled	1,130.00 FS	*1,130.00 FS
11	1		*2K-BODY ADHESIVE	Necessary	406.76 FS	*406.76 FS
12	1		*2K-FULLSCHAUM	Necessary	144.94 FS	*144.94 FS
13	1		*ZINC SPRAY	Necessary	62.88 FS	*62.88 FS
14	1		*SEALANT CAN BE SPRAYED	Necessary	61.67 FS	*61.67 FS
15	1		*PROTETIVE LHR FENDER FILM	Necessary	50.30 FS	*50.30 FS
16	1		*RUBBER VALVE	Necessary	3.29 FS	*3.29 FS
17	1		*ALLOYWHEEL	Scratched	1,105.00 FS	*1,105.00 FS
18	1		*REAR AXLE BEAM	* Check	2,507.42 FS	*- FS
19	1		*STUB AXLE	* Check	275.33 FS	*- FS
20	1		*WHEEL BEARING WITH MOUNTI	* Check	575.29 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **11,173.18** **6,251.78**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WHEEL ALIGNMENT	New	360.00	360.00
2	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
3	CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	0.00
4	R&R RIM & BALANCE	New	50.00	50.00
5	R&R REAR AXLE BEAM (* Check)	New	2,520.00	0.00
6	R&R CTR CONSOLE TO R&R HANDBRAKE CABLE	New	840.00	0.00
7	LABOUR	New	5,040.00	4,200.00
8	SPRAY PAINTING	New	4,000.00	2,400.00
9	R&R REAR LUGGAGE TRIM	New	840.00	420.00
10	R&R REAR SEAT	New	840.00	420.00
11	REAR WATER LEAK TEST	New	840.00	0.00
12	TRANSFER DOOR MECHANISM	New	840.00	420.00
Gross Labour Cost (\$\$)			16,930.00	8,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >