Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CC4/III20009067/QGS3Q2 Our File No:

Date: 24/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant GBD5620H Insured Vehicle No: SHD3695J

Vehicle No:

Date of Loss: 23/08/2020 Nature of Claim: TP Claim No: MCT20080330

DESCRIPTION & IDENTIFICATION OF VEHICLE

GBD5620H Reg No:

Make & Model: ISUZU TFR86JDR, 2.5 D (M) Engine No: ML8648

Chassis No: Reg. Date: 08/12/2014 (Man. Year: 2014) MPATFR86JFT001309

Colour: White Odometer: 97783 km

Engine Capacity: 2499 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Fair Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 215/70 R15C Rear Tyre Size: 215/70 R15C Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,357.50	1,518.00	7,839.50	83.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,721.28	335.00	1,386.28	80.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,078.78	1,853.00	9,225.78	83.27
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	11,078.78	1,500.00	9,578.78	86.46
+ GST 7.00/7.00% (S\$)	775.51	105.00	670.51	86.46
Nett Amount (S\$)	11,854.29	1,605.00	10,249.29	86.46
+ Loss of Use (3.0 x S\$6	60.00/day) (S\$)	180.00		
Nett Liability (S\$) Global Sum Settlement (S\$)		1,785.00		
		1,750.00		

INSPECTION

Date of Assignment: 27/08/2020

Date Inspected: 02/09/2020 Inspected At: SMRT Automotive Services Pte Ltd

(Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: OI SUN PIN Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Oct 2020)

Parts: N/A ISUZU TFR86JDR 2.5 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBD5620H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Condition

Total Parts (S\$)

Repairer's

9,357.50

1,518.00

Amount

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts No. Qty Part No. Particulars

110.	city i ditiio.	i di dicalai 3	Contaition	repairer 3	Amount
1	1	*BADGE MODEL (WCP)	Serviceable	95.00 F	*- F
2	1	*BOOTLID / TAILGATE (WCP)	Serviceable	980.00 F	*- F
3	1	*CTR CROSSMEMBER (WCP)	Serviceable	1,100.00 F	*- F
4	1	*CTR REAR CROSSMEMBER (WCP)	Serviceable	1,100.00 F	*- F
5	1	*L/R LAMP ASSY (WCP)	Serviceable	310.00 F	*- F
6	1	*L/R WING (WCP)	Serviceable	890.00 F	*- F
7	1	*LICENSE PLATE LAMP (WCP)	Serviceable	120.00 F	*- F
8	1	*R/R LAMP ASSY (WCP)	Serviceable	310.00 F	*- F
9	1	*R/R WING (WCP)	Serviceable	890.00 F	*- F
10	1	*REAR BADGE (NPA)	Not Necessary	0.00 F	*- F
11	1	*REAR BUMPER CPL (WCP)	Dented	680.00 F	*680.00 F
12	1	*REAR COVER BUMPER (WCP)	Crushed	290.00 F	*290.00 F
13	1	*REAR END DOOR HANDLE (WCP)	Serviceable	200.00 F	*- F
14	1	*RR BUMPER LWR GARNIS (WCP)	Crushed	210.00 F	*210.00 F
15	1	*RR BUMPER REINFORCE (WCP)	Serviceable	550.00 F	*- F
16	1	*TAILGATE HANDLE (WCP)	Serviceable	200.00 F	*- F
17	1	*SENSOR REVERSE	Shorted	200.00 FS	*200.00 FS
18	3	*STICKER EM 1	Serviceable	400.00 FS	*-FS
19	1	*STICKER 70KM/H	Serviceable	20.00 FS	*- FS
20	1	*REAR NUMBER PLATE	Dented	20.00 FS	*20.00 FS
F=Fra	nchise part. S=SpcN	lett.	_		
		+ Margin on L,N Items	Sub Total (S\$)	8,565.00	1,400.00
		792.50	118.00		

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOTAL OF LABOUR.	New	875.00	175.00
2	TOTAL PAINT INCLUDING MATERIAL.	New	846.28	160.00
		Gross Labour Cost (S\$)	1,721.28	335.00
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >