

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20009071/QYF3E2

Date: 07/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800155521
Claimant Vehicle No : SLZ6007M	Insured Vehicle No :	SMG8982Y
Date of Loss: 25/08/2020	Nature of Claim: TP	Claim No: 1995690672SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ6007M	Engine No:	27195031130501
Make & Model:	MERCEDES-BENZ C200 KOMPRESSOR, 1.8 (A)	Chassis No:	WDD2040412A211147
Reg. Date:	25/02/2009 (Man. Year: 2008)	Odometer:	237562 km
Colour:	Black		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	27/08/2020	
Date Inspected:	01/09/2020 Inspected At:	Jingkia Car Services (HQ) BLK 10 AMK INDUSTRIAL PARK 2A, #05-09 AMK AUTO POINT Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: OI SUN PIN

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crumpled	0.00 F	*- F
2	1		*REAR BUMPER UPPER BRACKET	Broken	0.00 F	*- F
3	3		*REAR BUMPER CHROME	Necessary	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	2		*REAR BUMPER BRACKET	Broken	0.00 F	*- F
6	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	2		*FRONT HEAD REST PUMP	Jammed	0.00 F	*- F
					Total Parts (\$\$)	0.00 0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >