

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20009072/QES3Q2

**Date:** 13/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800144830

**Claimant**  
**Vehicle No :** SHD6273Z **Insured Vehicle No :** SLV2018D

Date of Loss: 21/08/2020 Nature of Claim: TP Claim No: 9116449364SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD6273Z</b>		
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Engine No:	2ZR1681351
Reg. Date:	24/06/2016 (Man. Year: 2015)	Chassis No:	JTDKN36UX05768190
Colour:	Maroon	Odometer:	270749 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	20,489.40	4,463.50	16,025.90	78.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,174.00	2,130.00	3,044.00	58.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>25,663.40</b>	<b>6,593.50</b>	<b>19,069.90</b>	<b>74.31</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,700.00</b>		
<b>Nett Amount (\$\$)</b>	<b>25,663.40</b>	<b>5,700.00</b>	<b>19,963.40</b>	<b>77.79</b>
<b>+ Loss of Use (8.0 x S\$50.00/day) (\$\$)</b>		400.00		
<b>+ Car Rental (8.0 x S\$104.86/day) (\$\$)</b>		838.88		
<b>+ Doc/Search Fee (\$\$)</b>		7.00		
<b>Nett Liability (\$\$)</b>		<b>6,945.88</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>6,940.00</b>		

### INSPECTION

Date of Assignment: 25/08/2020

Date Inspected: 25/08/2020 Inspected At:

SMRT Automotive Services Pte Ltd  
(Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 5.0 days

---

**Adjuster:** OI SUN PIN**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR (DISC 25%)	Crushed	458.60 F	*343.95 F
2	1		*BUMPER CLIPS (DISC 25%) 10pcs	Necessary	21.00 F	*15.75 F
3	1		*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Broken	94.80 F	*71.10 F
4	1		*BUMPER SIDE RETAINER RR/RH (DISC 25%)	Broken	94.80 F	*71.10 F
5	1		*TAILGATE ASY (DISC 25%)	Dented	1,007.90 F	*755.93 F
6	1		*TAILGATE DOOR GLASS MOULDING, RH (DISC 25%)	Necessary	29.40 F	*22.05 F
7	1		*TAILGATE DOOR GLASS MOUDLING, LH (DISC 25%)	Necessary	29.40 F	*22.05 F
8	1		*MOULDING BACK WINDOW, LOWER NO.1 (DISC 25%)	Necessary	29.40 F	*22.05 F
9	1		*END PANEL COVER, DECK TRIM, RR (DISC 25%)	Crushed	121.10 F	*90.83 F
10	1		*TAILGATE DOOR WEATHER STRIP (DISC 25%)	Cut	353.40 F	*265.05 F
11	1		*BUMPER FRT (DISC 25%)	Crushed	482.00 F	*361.50 F
12	1		*BUMPER CLIPS (DISC 25%) 10pcs	Necessary	16.10 F	*12.08 F
13	1		*EMBLEM FRONT (DISC 25%)	Crushed	86.50 F	*64.88 F
14	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
15	1		*SENSOR REVERSE (SN)	Shorted	180.00 F	*180.00 F
16	3		*SEALANT W/SCREEN (SN)	Necessary	111.00 F	*111.00 F
17	1		*NUMBER PLATE FRAME (SN)	Crushed	12.00 F	*12.00 F
18	1		*NUMBER PLATE (SN)	Crushed	15.00 F	*15.00 F
19	1		*FENDER FRT/RH	Serviceable	723.40 F	*- F
20	1		*NAME PLATE (HYBRID)	Serviceable	51.90 F	*- F
21	1		*BUMPER REINFORCEMENT REAR	Serviceable	205.70 F	*- F
22	1		*ARM SUB-ASSY, RR BUMPER RH	Serviceable	139.60 F	*- F
23	1		*ARM SUB-ASSY, RR BUMPER LH	Serviceable	139.60 F	*- F
24	1		*ANTENNA, ELECTRICAL LOWER REAR	Serviceable	157.40 F	*- F
25	1		*NUMBER PLATE	Serviceable	15.00 F	*- F
26	1		*NUMBER PLATE FRAME	Serviceable	12.00 F	*- F
27	1		*TAIL LAMP RH	Serviceable	557.80 F	*- F
28	1		*TAIL LAMP LH	Serviceable	548.40 F	*- F
29	2		*TAILGATE DOOR HINGE LH/RH	Serviceable	116.60 F	*- F
30	1		*TAILGATE DOOR LOCK	Serviceable	444.10 F	*- F
31	1		*TAILGATE LOCK, COVER	Serviceable	15.70 F	*- F
32	1		*BUMPER SUPPORT F/RH	Serviceable	76.40 F	*- F
33	1		*BUMPER SUPPORT F/LH	Serviceable	76.40 F	*- F
34	1		*BUMPER ENERGY ABSORBER FRT	Serviceable	78.80 F	*- F
35	1		*BUMPER REINFORCEMENT FRT	Serviceable	498.40 F	*- F
36	1		*ARM SUB-ASSY, FR BUMPER LH	Serviceable	250.40 F	*- F
37	1		*ARM SUB-ASSY, FR BUMPER RH	Serviceable	250.40 F	*- F
38	1		*BRACKET, FR BUMPER	Serviceable	110.40 F	*- F
39	1		*COVER, FR BUMPER HOLE LH	Serviceable	18.50 F	*- F
40	1		*COVER, FR BUMPER HOLE RH	Serviceable	18.50 F	*- F
41	1		*BUMPER GRILLE SUB-ASSY, LOWER	Serviceable	311.10 F	*- F
42	1		*WIRE, ENGINE ROOM, NO.3	Serviceable	242.00 F	*- F
43	1		*LENS & BODY, FR TURN LH	Serviceable	511.80 F	*- F
44	1		*LENS & BODY, FR TURN RH	Serviceable	511.80 F	*- F
45	1		*COVER, RADIATOR	Serviceable	122.80 F	*- F
46	1		*GRILLE, RADIATOR	Serviceable	310.60 F	*- F
47	1		*GRILLE, RADIATOR LOWER NO.2	Serviceable	94.60 F	*- F
48	1		*BUMPER LIP FRT	Serviceable	139.60 F	*- F
49	1		*BUMPER FRT ABSORBER LOWER	Serviceable	127.70 F	*- F
50	1		*UNDER COVER CENTER	Serviceable	448.30 F	*- F
51	1		*HOOD HINRE LH	Serviceable	55.90 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*HOOD HINGE RH	Serviceable	55.90 F	*- F
53	1		*SUPPORT SUB-ASSY	Serviceable	1,460.40 F	*- F
54	1		*HEAD LAMP LH	Serviceable	945.20 F	*- F
55	1		*HEAD LAMP RH	Serviceable	945.20 F	*- F
56	1		*BUMPER SEAL, RR LH	Serviceable	88.90 F	*- F
57	1		*BUMPER SEAL, RR RH	Serviceable	65.70 F	*- F
58	1		*BUMPER LIP COVER RR/LH	Serviceable	72.20 F	*- F
59	1		*BUMPER LIP COVER RR/RH	Serviceable	118.10 F	*- F
60	1		*BUMPER LIP REAR	Serviceable	228.90 F	*- F
61	1		*UNDER COVER SUB-ASSY, RR FLOOR	Serviceable	514.50 F	*- F
62	1		*UNDER COVER RR SHIELD	Serviceable	63.90 F	*- F
63	1		*END PANEL	Serviceable	602.10 F	*- F
64	1		*SEALANT SIKAFLEX	Serviceable	37.00 F	*- F
65	1		*SPARE TYRE PANEL	Serviceable	667.70 F	*- F
66	1		*HOOD PANEL	Repair	748.10 F	*- F
67	1		*BUMPER REINFORCEMENT REAR (DISC 25%)	Bent	205.70 F	*154.28 F
68	1		*ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	Bent	139.60 F	*104.70 F
69	1		*ARM SUB-ASSY, RR BUMPER LH (DISC 25%)	Bent	139.60 F	*104.70 F
70	1		*END PANEL COVER, DECK TRIM HOLE (DISC 25%)	Crushed	46.10 F	*34.58 F
71	1		*BUMPER ENERGY ABSORBER FRT (DISC 25%)	Crushed	78.80 F	*59.10 F
72	1		*BUMPER REINFORCEMENT FRT (DISC 25%)	Bent	498.40 F	*373.80 F
73	1		*ARM SUB-ASSY, FR BUMPER LH (DISC 25%)	Bent	250.40 F	*187.80 F
74	1		*ARM SUB-ASSY, FR BUMPER RH (DISC 25%)	Bent	250.40 F	*187.80 F
75	1		*BRACKET, FR BUMPER (DISC 25%)	Crushed	110.40 F	*82.80 F
76	1		*BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%)	Cracked	311.10 F	*233.33 F
77	1		*GRILLE, RADIATOR LOWER NO.2 (DISC 25%)	Cracked	94.60 F	*70.95 F
78	1		*BUMPER LIP REAR (DISC 25%)	Crushed	228.90 F	*171.68 F
79	1		*ANTENNA, ELECTRICAL LOWER REAR (DISC 10%)	Cracked	157.40 F	*141.66 F
80	1		*BUMPER LIP COVER RR/RH	Serviceable	118.10 F	*- F
81	1		*END PANEL	Repair	602.10 F	*- F

F=Franchise part.

**Total Parts (S\$)    20,489.40    4,463.50**

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING & BODYWORK.	New	1,464.00	850.00
2	SPRAY PAINT.	New	2,990.00	1,000.00
3	TO REMOVE AND REFIX REAR WINDSCREEN.	New	120.00	100.00
4	TO REMOVE AND REFIX TAILGATE GLASS.	New	120.00	80.00
5	TO TRANSFER REAR TAILGATE MECHANISM.	New	120.00	50.00
6	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	30.00
7	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
8	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	20.00
9	TO WASH AND VACUUM.	New	60.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>5,174.00</b>	<b>2,130.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >