

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 1628H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED	600.20	600.20
1	REAR BUMPER SIDE RETAINER N/S	NECESSARY / BENT	66.50	66.50
1	REAR BUMPER REINFORCEMENT	BENT	388.50	388.50
1	REAR BUMPER REFLECTOR N/S	GRAZED	128.50	128.50
1	REAR BUMPER LOWER TRAY N/S	TORN	145.80	145.80
1	REAR BUMPER SIDE BRACKET N/S	CRACKED	62.50	62.50
1	TAILLAMP N/S	NOT NECESSARY	488.50	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	385.60	-
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	899.20	-
	LESS 20% DISCOUNT		-	-278.40
			3,165.30	1,113.60
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	300.00	250.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
			400.00	300.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	TO RESET & REPROGRAMME SYSTEM.		100.00	80.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR FENDER N/S.		800.00	500.00
	TO PUTTY & SPRAY PAINTING.		800.00	750.00
			-	-

Report Ref No. CS/TP20009074/Uvf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
			-	-
			2,000.00	1,480.00
	GRAND TOTAL		5,565.30	2,893.60

RECOMMENDED COST OF LUMP SUM REPAIRS		2,300.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/TP20009074/Uvf3e2

CHUA KANG SENG

Licensed Appraiser