

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009075/QRS3Q2

Date: 26/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700019305

Claimant
Vehicle No : GBH3387Z **Insured Vehicle No :** SLP9098H

Date of Loss: 20/08/2020 Nature of Claim: TP Claim No: 3335889468SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH3387Z	Engine No:	HIDDEN
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y10K210274
Reg. Date:	25/04/2018 (Man. Year: 2018)	Odometer:	110775 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,367.00	1,488.75	1,878.25	55.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	580.00	980.00	62.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,927.00	2,068.75	2,858.25	58.01
Approved Total (Overridden) (\$\$)		1,550.00		
(\$\$)	4,927.00	1,550.00	3,377.00	68.54
+ GST 7.00/7.00% (\$\$)	344.89	108.50	236.39	68.54
Nett Amount (\$\$)	5,271.89	1,658.50	3,613.39	68.54

INSPECTION

Date of Assignment: 27/08/2020

Date Inspected: 05/10/2020 Inspected At:

My Car Consultant Pte Ltd - Ubi (HQ)
53 Ubi Ave 1, #01-33 Paya Ubi
Industrial Park
Singapore 408934

Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SIDE GATE RH	Dented	1,985.00 FL	*1,985.00 FL
2	1		*REAR SIDE GATE LOCK RH	Repair	159.00 FL	*- FL
3	1		*REAR TAILLAMP RH	Serviceable	212.00 FL	*- FL
4	1		*REAR SAFETY BAR	Serviceable	800.00 FS	*- FS
5	1		*REAR SIDE SAFETY RAILING RH	Serviceable	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,956.00	1,985.00
- List Item Discount on L Items 25.00/25.00% (\$)	589.00	496.25

Total Parts (\$)	3,367.00	1,488.75
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT WELD ,CUT ,ADJUST AND KNOCK	New	600.00	250.00
2	TO PUTTY ,SRPAY PAINT ,POLISH WAX	New	600.00	300.00
3	TO SPRAY TUFF COAT	New	300.00	30.00
4	CHECK AND REFIX WIRING AND BULB	New	60.00	0.00
Gross Labour Cost (\$\$)			1,560.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >