

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009078/ADS3Q2

Date: 06/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100502275-03

Claimant

Vehicle No : SJM2910Z

Insured Vehicle No : GZ2509S

Date of Loss: 24/08/2020

Nature of Claim: TP

Claim No: 4430088772SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJM2910Z

Make & Model: HYUNDAI AVANTE, 1.6 HD (M)

Engine No: G4FC8U574507

Reg. Date: 29/12/2008 (Man. Year: 2008)

Chassis No: KMHDU41BR9U658732

Colour: Silver

Odometer: 120894 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes

Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: KAPSEN 6 mm

Rear Left Side: KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm

Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	0.00	0.00	
Approved Total (Overridden) (\$\$)		8,000.00		
Nett Amount (\$\$)	0.00	8,000.00	-8,000.00	
+ Loss of Use (21.0 x S\$80.00/day) (\$\$)		1,680.00		
Nett Liability (\$\$)		9,680.00		

INSPECTION

Date of Assignment: 27/08/2020

Date Inspected: 28/08/2020 **Inspected At:**

Stk Auto (s) Pte Ltd (HQ)

8 kaki bukit ave4, #03-21

Singapore 415875

Estimated Period of Repair: 0.0 days

Adjuster: ADRIAN LING

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >