3/24/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG20009079/QRA3Q2

Date:

24/03/2021

REFERENCE

Handling Insurer: **Claimant Vehicle** AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900233814

No:

SMB3591B

Insured Vehicle No:

SMP9603M

Date of Loss:

18/08/2020

Nature of Claim:

TP

Claim No:

6845050581SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Rea No:

SMB3591B

Make & Model:

ALEXANDER DENNIS ENVIRO500, 8.8 D (A)

Engine No: Chassis No: 22143626

Reg. Date:

04/05/2015 (Man. Year: 2014)

Odometer:

208820 km

SFD76CLR5EMTL3763

Colour: **Engine Capacity:**

Silver 8849 cc N/A

Market Value/New Car Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable): Yes

Handbrake (Serviceable):

Yes **Engine Modification:** No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

305/70 R22.5 Firenza 6 mm Rear Tyre Size: Rear Left Side:

305/70 R22.5 Firenza 6 mm

Front Right Side:

Firenza 6 mm

Rear Right Side:

Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,597.24	0.00	4,597.24	100.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,938.00	1,316.00	622.00	32.09
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	6,535.24	1,316.00	5,219.24	79.86

700.00 + Loss of Use (2.0 x S\$350.00/day) (S\$) (S\$) 2,016.00 1,008.00 Liable Amount (50.00%) (S\$) + Doc/Search Fee (S\$) 7.00

> Nett Liability (S\$) 1,015.00

INSPECTION

Date Inspected:

Date of Assignment:

25/08/2020

25/08/2020 Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN Manager:

Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*EXIENOX PANEL ,RAD ACCESS DOOR R/H	Repair	2,485.08 F	*- F
2	1	*PANEL EXTERIOR :R/H,FOR ADL DD BUS	Repair	408.91 F	*- F
3	1	*POD ,TAIL LIGHT :R/H ,FOR ADL E500 DD BUS	Repair	1,703.25 F	*- F
F=Fra	anchise part.		_		
			Total Parts (S\$)	4,597.24	0.00
		Report was unsubmitted during this	nrint out		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,060.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	878.00	786.00
	Gross Labour Cost (S\$)		1,938.00	1,316.00
	Report was unsubmitted during this p	rint-out.		

< END OF ESTIMATES >