



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 3861Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	CRUMPLED	480.10	480.10
1	FRONT LH LIGHT	CRACKED	378.20	378.20
1	FRONT LH FENDER	CRUMPLED	578.10	578.10
1	FRONT LH RETAINER	BROKEN	123.20	123.20
1	FRONT LH INNER SHIELD	DEFORMED	178.30	178.30
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	879.20	-
1	FRONT FOG LAMP LH	SERVICEABLE	379.20	-
1	REINFORCEMENT	BENT	378.20	378.20
1	FRONT BONNET (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT LH DOOR (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT LH CHASSIS (NPA)	TO REPAIR SEE LABOUR	-	-
1	BUMPER UNDER TRAY (ADDITIONAL)	CRUMPLED	348.20	348.20
1	AIR INTAKE BOX (ADDITIONAL)	DEFORMED	269.10	269.10
1	FENDER INNER BRACKET (ADDITIONAL)	BENT	88.10	88.10
	LESS 25% DISCOUNT		-	-705.38
			4,079.90	2,116.12
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET INNER SHIELD CLIPS (SN)	NECESSARY	50.00	30.00
1	NUMBER PLATE (SN)	SERVICEABLE	50.00	-
1	NUMBER PLATE FRAME (SN)	SERVICEABLE	50.00	-
			200.00	60.00
	<b><u>LABOUR</u></b>			
	TOWING.		120.00	80.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL,FRONT BONNET,FRONT LH DOOR AND FRONT LH CHASSIS.		1,000.00	600.00
	SPRAY PAINTING.		800.00	800.00

Report Ref No. CS/FCI20009081/Qtf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK WIRING.		200.00	30.00
	TO APPLY ANTI RUST.		120.00	50.00
			2,240.00	1,560.00
GRAND TOTAL			6,519.90	3,736.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CS/FCI20009081/Qtf3e2

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.