



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2101365

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 05/03/2021
Reference CC3/CTI20009082/Qea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHB 1432A
Insured Veh. SMM 2245A
Claim No. SNM20D203075
Policy No. DMPCSNW00037282000
Accident Date 25/08/2020
Inspection Date 26/08/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI20009082/Qea3q2 Date: 05/03/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMM 2245A	Veh. Inspected	SHB 1432A	
Policy No.	DMPCSNW00037282000	Coverage (\$)	0.00	
Claim No.	SNM20D203075	Excess (\$)	0.00	
Assign From		Assign Date	26/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JTDKN36U605758448	Colour	MAROON	
Odometer	521090 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FIRENZA	6 mm	
L/H Front Tyre	195/65 R15	FIRENZA	6 mm	
R/H Rear Tyre	195/65 R15	FIRENZA	6 mm	
L/H Rear Tyre	195/65 R15	FIRENZA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/08/2020	Inspection Date	26/08/2020	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1432A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	WIPER WASHER JAR (DISC 25%)	CRUSHED	180.10	135.08
1	FENDER LINER FRT/RH (DISC 25%)	CUT	171.70	128.78
1	BUMPER FRT (DISC 25%)	CRUSHED	482.00	361.50
10	BUMPER CLIPS @ \$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	COVER, FR BUMPER HOLE RH (DISC 25%)	SCRATCHED	18.50	13.88
1	HEAD LAMP RH (DISC 10%)	SCRATCHED	945.20	850.68
1	LENS & BODY, FR TURN RH (DISC 10%)	SCRATCHED / CRACKED	511.80	460.62
1	WIRE, ENGINE ROOM, NO.3	SERVICEABLE	242.00	-
1	SUPPORT SUB-ASSY	SERVICEABLE	1,460.40	-
1	WIPER WASHER INLET	SERVICEABLE	36.90	-
1	FENDER FRT/RH	SERVICEABLE	723.40	-
1	NAME PLATE (HYBRID)	SERVICEABLE	51.90	-
1	FENDER, LINER PAD, FR WHEEL, RH	SERVICEABLE	49.30	-
1	TYRE	SERVICEABLE	126.74	-
1	WHEEL DISC, FRONT	SERVICEABLE	1,484.20	-
1	BUMPER ENERGY ABSORBER FRT	SERVICEABLE	78.80	-
1	BUMPER REINFORCEMENT FRT	SERVICEABLE	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	SERVICEABLE	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH	SERVICEABLE	250.40	-
1	BUMPER SUPPORT F/RH	SERVICEABLE	76.40	-
1	FOG LAMP RH	SERVICEABLE	295.20	-
1	BRACKET, FR TURN LOWER RH	SERVICEABLE	26.00	-
1	BRACKET, FR TURN UPPER RH	SERVICEABLE	24.40	-
1	BRACKET, FR TURN CENTER RH	SERVICEABLE	58.20	-
1	BUMPER FRT ABSORBER LOWER	SERVICEABLE	127.70	-
1	BUMPER LIP FRT	TO REPAIR SEE LABOUR	139.60	-
1	BUMPER GRILLE SUB-ASSY, LOWER	TO REPAIR SEE LABOUR	311.10	-
1	ADVERTISEMENT STICKER (SN)	NOT NECESSARY	148.44	-

Report Ref No. CC3/CTI20009082/Qea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER ENERGY ABSORBER FRT (DISC 25%) (ADDITIONAL)	CRUSHED	78.80	59.10
1	BUMPER REINFORCEMENT FRT (DISC 25%) (ADDITIONAL)	DENTED	498.40	373.80
			9,362.48	2,395.52
	LABOUR			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF BUMPER LIP FRT AND BUMPER GRILLE SUB-ASSY, LOWER.		845.00	200.00
	SPRAY PAINT.		1,296.00	300.00
	TOEWING CHARGE.	NOT NECESSARY	56.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	20.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	200.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPAIR FRT FENDER RH. (ADDITIONAL)		150.00	100.00
			3,127.00	640.00
GRAND TOTAL			12,489.48	3,035.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,550.00

Report Ref No. CC3/CTI20009082/Qea3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 1432A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 1432A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

