

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20009083/BTF3E2

Date: 16/09/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00001952000	
Claimant Vehicle No :	SKN4761G	Insured Vehicle No :	SML7753Y	
Date of Loss:	27/08/2020	Nature of Claim:	TP	Claim No: SNM20D203067/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN4761G			
Make & Model:	MAZDA 3, 1.5 L (A)	Engine No:	P520212041	
Reg. Date:	18/06/2014 (Man. Year: 2014)	Chassis No:	JM6BM42A8E0121519	
Colour:	Grey	Odometer:	223882 km	
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	CST 6 mm	Rear Left Side:	CST 6 mm
Front Right Side:	CST 6 mm	Rear Right Side:	CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,815.14	8,265.60	12,549.54	60.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,130.00	2,240.00	4,890.00	68.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,945.14	10,505.60	17,439.54	62.41
Approved Total (Overridden) (S\$)		8,400.00		
Nett Amount (S\$)	27,945.14	8,400.00	19,545.14	69.94

INSPECTION

Date of Assignment:	29/08/2020			
Date Inspected:	28/08/2020	Inspected At:	Team Autopro Pte Ltd (Sin Ming) 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722	
Estimated Period of Repair:	7.0 days			

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 Sep 2020)	
Parts:	N/A	MAZDA 3 1.5 L (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKN4761G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,358.00 FL	*1,215.00 FL
2	1		*BOOTLID LOGO	Necessary	88.20 FL	*65.80 FL
3	1		*BOOTLID EMBLEM MAZDA	Necessary	68.90 FL	*49.20 FL
4	1		*BOOTLID EMBLEM SKYACTIV	Necessary	87.20 FL	*74.70 FL
5	2		*BOOTLID LAMP	Broken	1,378.60 FL	*825.00 FL
6	1		*BOOTLID INNER TRIM BOARD	Not Damaged	187.30 FL	*- FL
7	1		*BOOTLID INNER LOCK	Jammed	190.80 FL	*177.30 FL
8	1		*BOOTLID INNER LOCK STRIKER	Not Damaged	68.10 FL	*- FL
9	2		*BOOTLID HINGE	Not Damaged	385.20 FL	*- FL
10	1		*BOOTLID ANTENNA SENSOR	Not Damaged	358.60 FL	*- FL
11	1		*REAR BUMPER	Broken	1,096.70 FL	*1,096.70 FL
12	2		*REAR BUMPER LOWER BRACKET	No such part	96.00 FL	*- FL
13	2		*REAR BUMPER SIDE RETAINER	Necessary	137.80 FL	*137.80 FL
14	1		*REAR BUMPER REINFORCEMENT	Dented	684.20 FL	*684.20 FL
15	2		*REAR BUMPER REFLECTOR	Not Necessary	156.46 FL	*- FL
16	2		*REAR BUMPER TOW CAP	Not Necessary	82.00 FL	*- FL
17	1		*REAR END PANEL	Dented	730.40 FL	*619.00 FL
18	1		*REAR END PANEL TOP GARNISH	Broken	109.40 FL	*109.40 FL
19	2		*REAR FENDER INNER TRIM BOARD	Not Damaged	640.00 FL	*- FL
20	2		*TAILLAMP	Broken	1,793.80 FL	*1,793.80 FL
21	2		*TAILLAMP LOWER BRACKET	No such part	490.00 FL	*- FL
22	1		*BONNET	Not Damaged	990.00 FL	*- FL
23	1		*BONNET INNER LOCK	Not Damaged	188.00 FL	*- FL
24	1		*FRONT BUMPER	Broken	1,026.20 FL	*1,026.20 FL
25	1		*FRONT BUMPER TOP BASE	No such part	385.80 FL	*- FL
26	1		*FRONT BUMPER INNER TOP GARNISH	No such part	412.50 FL	*- FL
27	2		*FRONT BUMPER SIDE RETAINER	Necessary	90.00 FL	*90.00 FL
28	1		*FRONT BUMPER INNER SPONGE	No such part	109.80 FL	*- FL
29	1		*FRONT BUMPER REINFORCEMENT	No such part	598.60 FL	*- FL
30	1		*FRONT BUMPER GRILLE	Broken	782.60 FL	*345.20 FL
31	1		*FRONT BUMPER GRILLE LOGO	Necessary	68.00 FL	*12.00 FL
32	2		*FRONT BUMPER GRILLE CHROME GARNISH	Broken	437.20 FL	*365.00 FL
33	1		*FRONT BUMPER LOWER GRILLE	Not Damaged	285.36 FL	*- FL
34	1		*FRONT BUMPER TOW CAP	Not Damaged	46.80 FL	*- FL
35	2		*FRONT BUMPER FOG LAMP GARNISH	Not Necessary	583.60 FL	*- FL
36	2		*FRONT BUMPER SIGNAL LAMP	Not Necessary	357.80 FL	*- FL
37	1		*FRONT SUPPORT PANEL	Not Damaged	593.20 FL	*- FL
38	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Damaged	147.60 FL	*- FL
39	1		*HEADLAMP (2PCS)	Broken (1Pc Only)	3,778.40 FL	*1,145.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*HEADLAMP LOWER BRACKET	Not Damaged	494.60 FL	*- FL
41	1		*A/C CONDENSER	Not Damaged	853.80 FL	*- FL
42	1		*RADIATOR	Not Damaged	863.90 FL	*- FL
43	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
44	1		*BOOTLID SEALANT	Not Necessary	100.00 FS	*- FS
45	2		*BOOTLID LAMP SEAL	Not Necessary	120.00 FS	*- FS
46	2		*BOOTLID LAMP CLIPS	Not Necessary	100.00 FS	*- FS
47	1		*BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
49	2		*REVERSE SENSOR	Short Circuit	500.00 FS	*200.00 FS
50	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
51	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
52	2		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	100.00 FS	*- FS
53	2		*TAILLAMP CLIPS	Not Necessary	100.00 FS	*- FS
54	2		*TAILLAMP SEAL	Not Necessary	120.00 FS	*- FS
55	1		*REAR NUMBER PLATE W/CASING	Not Damaged	80.00 FS	*- FS
56	1		*BONNET SEALANT	Not Necessary	100.00 FS	*- FS
57	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
58	1		*FRONT BUMPER GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
59	1		*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
60	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
61	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
62	1		*FRONT NUMBER PLATE W/CASING	Bent	80.00 FS	*50.00 FS
63	1		*A/C FLUID	Not Necessary	80.00 FS	*- FS
64	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,471.42	10,232.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,656.28	1,966.40
Total Parts (\$\$)	20,815.14	8,265.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R BOOTLID COMPONENT	New	150.00	50.00
2	R&R REVERSE SENSOR	New	100.00	60.00
3	REAR UPHOLSTERY	New	200.00	0.00
4	REAR RUST PROOFING	New	200.00	30.00
5	REAR CHECK WIRING	New	80.00	50.00
6	CONDUCT WATER LEAK TEST	New	120.00	0.00
7	REAR PANEL BEAT	New	1,600.00	600.00
8	R&R A/C CONDENSER	New	150.00	0.00
9	R&R RADIATOR	New	150.00	0.00
10	FRONT UPHOLSTERY	New	200.00	0.00
11	FRONT RUST PROOFING	New	100.00	0.00
12	FRONT CHECK WIRING	New	80.00	50.00
13	FRONT PANEL BEAT	New	1,200.00	400.00
14	FRONT SPRAY PAINTING	New	1,200.00	200.00
15	REAR SPRAY PAINTING	New	1,600.00	800.00
Gross Labour Cost (S\$)			7,130.00	2,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >