

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
AUTO & GENERAL INSURANCE (S) PL Ref: CS/AGI20009086/Avf3q2					
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date: 03-11-2020 Code: AGI		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJH 5034J	Veh. Inspected	SML 9109U	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10007113	Excess (\$)	0.00	
	Assign From	STANLEY LAI	Assign Date	27/08/2020	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA WISH	c.c	1794	
	Engine No.	HIDDEN	Year of Reg.	2007	
	Chassis No.	ZNE100312239	Colour	GREY	
	Odometer	229933	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/50 R16	TOURADOR	6 mm	
	L/H Front Tyre	205/50 R16	TOURADOR	6 mm	
	R/H Rear Tyre	205/50 R16	TOURADOR	6 mm	
	L/H Rear Tyre	205/50 R16	TOURADOR	6 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
_	DAMAGES SEE DETAILS.				
5.	14		Information	00/00/0000	
	Accident Date	25/08/2020	Inspection Date	28/08/2020	
	Survey held at				
-	Repairer	Repairer SK AUTOMOBILE PTE LTD			
5a.	Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
	B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				
5b.		Estimate Days of Repair			

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: