



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3508H

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|---------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | IONIQV2&3 COVER-FR BUMPER | SCRATCHED | 430.90 | 430.90 |
| 1 | IONIQVC BRACKET-FR BUMPER | SERVICEABLE | 35.00 | - |
| 1 | IONIQVC BRACKET-FR BUMPER | SERVICEABLE | 28.00 | - |
| 1 | IONIQV1-3 LAMP ASSY-HEAD | SCRATCHED | 1,993.65 | 1,993.65 |
| 1 | IONIQV1-3 LAMP ASSY-DAY R | SERVICEABLE | 642.50 | - |
| 1 | IONIQV1-3 MOULDING-FRONT | SCRATCHED | 93.60 | 93.60 |
| 1 | IONIQVC PANEL-FENDER RH | SERVICEABLE | 588.80 | - |
| 1 | IONIQVC EMBLEM-BLUE DRIVE | NOT NECESSARY | 26.60 | - |
| | LESS 20% DISCOUNT | | -767.81 | -503.63 |
| | | | 3,071.24 | 2,014.52 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING. | | 500.00 | 320.00 |
| | SPRAYPAINT ON AFFECTED AREA. | | 450.00 | 200.00 |
| | CHECK ALL LIGHTING. | | 50.00 | 30.00 |
| | TUFF COAT ON AFFECTED PARTS. | NOT NECESSARY | 50.00 | - |
| | | | 1,050.00 | 550.00 |
| | GRAND TOTAL | | 4,121.24 | 2,564.52 |
| | RECOMMENDED COST OF REPAIRS (CONFIRMED) | | | 2,564.52 |

Report Ref No. NS/INC20009091/R1vf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.