

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC20009091/R1vf3e2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	02-09-2020 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SKZ 6373S	Veh. Ir	nspected	SHA 3508H	
	Policy No.	5107658332-01	Cover	age (\$)	0.00	
	Claim No.	MT/1101404-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	27/08/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2018	
	Chassis No.	KMHC851CVKU114841	Colou	r	BLUE	
	Odometer	285954	Steering		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	LAKE	6 mm	
	L/H Front Tyre	195/65 R15	WEST	LAKE	6 mm	
	R/H Rear Tyre	195/65 R15	WEST		6 mm	
	L/H Rear Tyre	195/65 R15	WEST		6 mm	
4.	<u> </u>					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	26/08/2020	Insped	tion Date	27/08/2020	
	Survey held at	at COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					