

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20009092/AGA3Q2  
**Date:** 30/03/2021

### REFERENCE

|                                                        |                               |                        |
|--------------------------------------------------------|-------------------------------|------------------------|
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. | Policy No: 0999993856         |                        |
| Claimant Vehicle No : GBK3799C                         | Insured Vehicle No : SMM9189H |                        |
| Date of Loss: 25/08/2020                               | Nature of Claim: TP           | Claim No: 2335293205SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                                                       |                               |  |
|-------------------------------------------------------|-------------------------------|--|
| Reg No: <b>GBK3799C</b>                               |                               |  |
| Make & Model: PEUGEOT PARTNER, 1.5 (A)                | Engine No: 10Q4DR0016129      |  |
| Reg. Date: 02/07/2020 (Man. Year: 2020)               | Chassis No: VR3EFYHZRLJ639629 |  |
| Colour: Black                                         | Odometer: 2633 km             |  |
| Engine Capacity: 1499 cc                              |                               |  |
| Market Value/New Car Price: N/A                       |                               |  |
| Sum Insured (\$\$): <b>Market Value/New Car Price</b> |                               |  |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                              |                             |                              |
|------------------------------|-----------------------------|------------------------------|
| General Condition:           | Steering (Serviceable): Yes | Footbrake (Serviceable): Yes |
| Handbrake (Serviceable): Yes | Engine Modification: No     | Pre-accident Condition:      |

### CONDITION OF TYRES

|                                 |                                |
|---------------------------------|--------------------------------|
| Front Tyre Size: 205/60 R16     | Rear Tyre Size: 205/60 R16     |
| Front Left Side: Michelin 6 mm  | Rear Left Side: Michelin 6 mm  |
| Front Right Side: Michelin 6 mm | Rear Right Side: Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                                   | Repairer's       | Adjuster's       | Difference      | Diff %       |
|--------------------------------------------------|------------------|------------------|-----------------|--------------|
| Parts                                            | 13,134.50        | 7,954.00         | 5,180.50        | 39.44        |
| Miscellaneous Items                              | 0.00             | 0.00             | 0.00            |              |
| Labour                                           | 3,480.00         | 2,220.00         | 1,260.00        | 36.21        |
| Paintwork Labour                                 | 0.00             | 0.00             | 0.00            |              |
| Towing                                           | 0.00             | 0.00             | 0.00            |              |
| <b>Calculated Gross Total (\$\$)</b>             | <b>16,614.50</b> | <b>10,174.00</b> | <b>6,440.50</b> | <b>38.76</b> |
| <b>Approved Total (Overridden) (\$\$)</b>        |                  | <b>8,100.00</b>  |                 |              |
| <b>Nett Amount (\$\$)</b>                        | <b>16,614.50</b> | <b>8,100.00</b>  | <b>8,514.50</b> | <b>51.25</b> |
| <b>+ Car Rental (8.0 x S\$100.00/day) (\$\$)</b> |                  | 800.00           |                 |              |
| <b>+ Doc/Search Fee (\$\$)</b>                   |                  | 7.45             |                 |              |
| <b>+ Other Costs (\$\$)</b>                      |                  | 80.00            |                 |              |
| <b>Nett Liability (\$\$)</b>                     |                  | <b>8,987.45</b>  |                 |              |

### INSPECTION

|                                      |               |                                                                                        |
|--------------------------------------|---------------|----------------------------------------------------------------------------------------|
| Date of Assignment: 26/08/2020       |               |                                                                                        |
| Date Inspected: 26/08/2020           | Inspected At: | Fong Motors (HQ)<br>1 Kaki Bukit Ave 6 #01-45, Autobay@ Kaki Bukit<br>Singapore 417883 |
| Estimated Period of Repair: 9.0 days |               |                                                                                        |

3/30/2021

Adjuster Report

**Adjuster:** ADRIAN LING

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                                  | Condition            | Repairer's  | Amount       |
|-----|-----|----------|----------------------------------------------|----------------------|-------------|--------------|
| 1   | 1   |          | *REAR FENDER RH                              | Distorted            | 1,890.00 FL | *1,890.00 FL |
| 2   | 1   |          | *REAR FENDER INNER SHIELD RH                 | Cut                  | 175.00 FL   | *175.00 FL   |
| 3   | 5   |          | *REAR FENDER INNER SHIELD CLIPS RH           | Necessary            | 50.00 FL    | *30.00 FL    |
| 4   | 1   |          | *REAR FENDER INNER SHIELD HOLDER RH          | Not Necessary        | 145.00 FL   | *- FL        |
| 5   | 1   |          | *REAR TAILGATE CABIN RUBBER WEATHERSTRIP     | Not Necessary        | 470.00 FL   | *- FL        |
| 6   | 1   |          | *REAR TAILGATE RH                            | Dented               | 1,950.00 FL | *1,950.00 FL |
| 7   | 2   |          | *REAR TAILGATE HINGES U/L RH                 | Bent                 | 450.00 FL   | *450.00 FL   |
| 8   | 1   |          | *REAR TAILGATE CHECKER ASSY RH               | Damaged              | 250.00 FL   | *250.00 FL   |
| 9   | 1   |          | *REAR TAILGATE INNER TRIMBOARD RH            | Not Necessary        | 320.00 FL   | *- FL        |
| 10  | 1   |          | *REAR TAILGATE RUBBER WEATHERSTRIP RH        | Not Necessary        | 210.00 FL   | *- FL        |
| 11  | 2   |          | *REAR TAILGATE MECHANISM LOCK U/L RH         | Damaged (1 PCS ONLY) | 680.00 FL   | *340.00 FL   |
| 12  | 2   |          | *REAR TAILGATE MECHANISM LOCK STRIKER U/L RH | Not Necessary        | 440.00 FL   | *- FL        |
| 13  | 1   |          | *REAR TAILGATE LOGO EMBLEM                   | Necessary            | 150.00 FL   | *150.00 FL   |
| 14  | 1   |          | *REAR TAILLAMP RH                            | Cracked              | 380.00 FL   | *380.00 FL   |
| 15  | 1   |          | *REAR TAILLAMP PANEL RH                      | Dented               | 950.00 FL   | *600.00 FL   |
| 16  | 1   |          | *REAR END PANEL                              | Dented               | 680.00 FL   | *680.00 FL   |
| 17  | 1   |          | *REAR END PANEL CORNER MEMBER RH             | Repair               | 370.00 FL   | *- FL        |
| 18  | 1   |          | *REAR END PANEL TOP GARNISH RH               | Not Necessary        | 350.00 FL   | *- FL        |
| 19  | 1   |          | *REAR BUMPER (CENTER)                        | Distorted            | 490.00 FL   | *490.00 FL   |
| 20  | 1   |          | *REAR BUMPER CORNER GARNISH RH               | Distorted            | 420.00 FL   | *420.00 FL   |
| 21  | 1   |          | *REAR BUMPER SIDE RETAINER L/R               | O/S Damaged          | 420.00 FL   | *210.00 FL   |
| 22  | 2   |          | *REAR BUMPER CORNER HOLDER L/R               | Not Necessary        | 420.00 FL   | *- FL        |
| 23  | 1   |          | *REAR BUMPER TOWING COVER                    | Missing              | 115.00 FL   | *115.00 FL   |
| 24  | 1   |          | *REAR BUMPER REINFORCEMENT BEAM              | Bent                 | 380.00 FL   | *380.00 FL   |
| 25  | 1   |          | *REAR EXHAUST SILENCER BOX                   | Not Necessary        | 1,130.00 FL | *- FL        |
| 26  | 1   |          | *REAR EXHAUST SILENCER BOX RUBBER MOUNTING   | Not Necessary        | 170.00 FL   | *- FL        |
| 27  | 1   |          | *REAR TAILGATE GLASS SEALANT                 | Necessary            | 80.00 FS    | *50.00 FS    |
| 28  | 1   |          | *REAR TAILGATE 70KM/H STICKER                | Necessary            | 15.00 FS    | *15.00 FS    |
| 29  | 1   |          | *REAR TAILLAMP LIGHT BULB RH                 | Not Necessary        | 12.00 FS    | *- FS        |
| 30  | 1   |          | *REAR TAILLAMP SIGNAL LIGHT BULB RH          | Not Necessary        | 9.00 FS     | *- FS        |
| 31  | 1   |          | *REAR TAILLAMP REVERSE LIGHT BULB RH         | Not Necessary        | 9.00 FS     | *- FS        |
| 32  | 1   |          | *SET REAR BUMPER CLIPS                       | Necessary            | 50.00 FS    | *30.00 FS    |
| 33  | 1   |          | *SET REAR BUMPER REVERSE SENSOR              | Damaged              | 250.00 FS   | *200.00 FS   |
| 34  | 1   |          | *REAR TRUNK PANEL TOP CARDBOARD              | Not Necessary        | 600.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                  |                 |
|----------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>14,480.00</b> | <b>8,805.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$)</b> | 1,345.50         | 851.00          |
| <b>Total Parts (\$)</b>                                  | <b>13,134.50</b> | <b>7,954.00</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                       | Particulars                                                                                                                               | Lab.Type | Repairer's      | Amount          |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>      |                                                                                                                                           |          |                 |                 |
| 1                        | TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING                                                                            | New      | 60.00           | 30.00           |
| 2                        | TO REMOVE & REFIX REVERSE SENSOR ASSY AND RETIFY FOR PROPER FUNCTIONING                                                                   | New      | 80.00           | 50.00           |
| 3                        | TO DIAGNOSE ,REPLACE /OR REPAIR TO RETIFTY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AND WHERE CONSISTENT TO THE ACCIDENT     | New      | 100.00          | 0.00            |
| 4                        | TO REMOVE REINSTALL REAR TAILGATE WINDSCREEN (TO FR)                                                                                      | New      | 150.00          | 80.00           |
| 5                        | TO REMOVE ,REINSTALL ROOF TOP UPHOLSTERY ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)                                                         | New      | 120.00          | 80.00           |
| 6                        | TO TRANSFER TAILGATE MECHANISM & WIRING ASSY (TO FR)                                                                                      | New      | 100.00          | 80.00           |
| 7                        | TO RESPRAY ,PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT                                         | New      | 1,200.00        | 800.00          |
| 8                        | TO REMOVE & REFIX EXHAUST SILENCER BOX ,REALIGN AND WHERE CONSISTENT TO THE ACCIDENT                                                      | New      | 100.00          | 0.00            |
| 9                        | TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE DAMAGED BODYPARTS ,REPAIR ,REALIGN BODY STRUCTURE & DAMAGED AND WHERE CONSISTENT TO THE ACCIDENT | New      | 1,200.00        | 1,000.00        |
| 10                       | TO SET ON CHASSIS BENCH ,ADJUST & ALIGN REAR CHASSIS                                                                                      | New      | 250.00          | 0.00            |
| 11                       | TO APPLY ANTI-RUST CHEMICAL ON REPAIRED & REPLACED PANEL                                                                                  | New      | 120.00          | 100.00          |
| Gross Labour Cost (\$\$) |                                                                                                                                           |          | <b>3,480.00</b> | <b>2,220.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >