

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7636U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RH WING MIRROR RH	SCRATCHED	670.00	670.00
	LESS 20% DISCOUNT		-134.00	-134.00
			536.00	536.00
	LABOUR			
	PANEL BEATING.		150.00	100.00
	SPRAY PAINTING CHARGE.		100.00	100.00
			250.00	200.00
	GRAND TOTAL		786.00	736.00

RECOMMENDED COST OF LUMP SUM REPAIRS		550.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC20009093/R1qf3s2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser