

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20009096/KVF3Q2

Date: 25/11/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSNA00105322001	
Claimant Vehicle No : SGE287E	Insured Vehicle No : SMM3794A	
Date of Loss: 26/08/2020	Nature of Claim: TP	Claim No: SNM20D203065/C02/TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGE287E	Engine No: G4ED6387461
Make & Model: HYUNDAI VERNA, 1.6 (A)	Chassis No: KMHCN41CR6U040956
Reg. Date: 08/03/2006 (Man. Year: 2006)	Odometer: 225046 km
Colour: Metallic Silver	
Engine Capacity: 1599 cc	
Market Value/New Car Price: N/A	
Sum Insured (\$\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/65 R14	Rear Tyre Size:	175/65 R14
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,081.52	1,730.56	350.96	16.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,160.00	890.00	270.00	23.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,241.52	2,620.56	620.96	19.16
Approved Total (Overridden) (\$\$)		2,100.00		
(\$\$)	3,241.52	2,100.00	1,141.52	35.22
+ GST 7.00/7.00% (\$\$)	226.91	147.00	79.91	35.22
Nett Amount (\$\$)	3,468.43	2,247.00	1,221.43	35.22

INSPECTION

Date of Assignment: 27/08/2020

Date Inspected: 31/08/2020 Inspected At:

Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A,
#01-09 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Nov 2020)
Parts:	143	HYUNDAI VERNA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGE287E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	1,432.30 FL	*1,432.30 FL
2	1		*REAR BOOT EMBLEM (VERNA)	Necessary	32.30 FL	*32.30 FL
3	1		*REAR BOOT INNER LOCK	Repair	38.70 FL	*- FL
4	1		*REAR BOOT RUBBER	Serviceable	61.10 FL	*- FL
5	1		*REAR BUMPER	Buckled	418.60 FL	*418.60 FL
6	2		*REAR BUMPER SIDE RETAINER LH & RH	Serviceable	64.00 FL	*- FL
7	15		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
8	1		*REAR BUMPER REINFORCEMENT	Repair	176.10 FL	*- FL
9	1		*REAR BUMPER SPONGE	Serviceable	98.80 FL	*- FL
10	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,551.90	2,113.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	470.38	382.64
Total Parts (\$\$)	2,081.52	1,730.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	10.00
2	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS	New	60.00	50.00
3	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
4	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR END PANEL INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	500.00	400.00
5	TO SPRAY REAR BOOT,REAR BUMPER END PANEL	New	500.00	400.00
Gross Labour Cost (\$\$)			1,160.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >