

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20009097/R1ES3Q2

Date: 05/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800072924-01

Claimant
Vehicle No : SLE3620Y **Insured Vehicle No :** SMA8107P

Date of Loss: 22/08/2020 **Nature of Claim:** TP **Claim No:** 4461048406SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE3620Y	Engine No:	F6281390B38B15A
Make & Model:	BMW 218I, 1.5 COUPE HID ABS SR (A)	Chassis No:	WBA2F120X0V758213
Reg. Date:	19/07/2016 (Man. Year: 2016)	Odometer:	47371 km
Colour:	Grey		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,186.45	3,892.10	1,294.35	24.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,021.00	10,533.00	1,488.00	12.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,207.45	14,425.10	2,782.35	16.17
+ GST 7.00/7.00% (S\$)	1,204.52	1,009.76	194.76	16.17
Nett Amount (S\$)	18,411.97	15,434.86	2,977.11	16.17
+ Loss of Use (12.0 x S\$60.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		16,156.86		

INSPECTION

Date of Assignment: 07/09/2020

Date Inspected: 07/09/2020 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*BLIND PLUG	Not Necessary	1.05 FS	*- FS
3	6		*PLASTIC NUT FOR COARSE THREADED PIN	Not Necessary	5.10 FS	*- FS
4	1		*ALLOY RIM 7.5JX17 STAR SPOKE 379	Scratched	921.70 FS	*921.70 FS
5	1		*REAR RH SIDE PANEL	Bent	1,333.95 FS	*1,333.95 FS
6	1		*RH REINFORCEMENT PLATE SILL	Serviceable	54.20 FS	*- FS
7	1		*RH B PILLAR REINFORCEMENT PLATE	Necessary	53.75 FS	*53.75 FS
8	1		*RH C PILLAR REINFORCEMENT PLATE	Necessary	69.70 FS	*69.70 FS
9	4		*PLASTIC NUT	Not Necessary	3.40 FS	*- FS
10	10		*BUMP STOP	Not Necessary	37.50 FS	*- FS
11	1		*REAR WINDOW	Not Necessary	626.30 FS	*- FS
12	1		*SIDE WINDOW	Not Necessary	293.05 FS	*- FS
13	1		*RH B COLUMN COVERING	Necessary	71.40 FS	*71.40 FS
14	1		*SET ADHESIVE PADS FOR ACE 2.0	Not Necessary	43.65 FS	*- FS
15	1		*CAVITY PROTECTION WAX REMOVER 500ML	Not Necessary	18.45 FS	*- FS
16	20		*BLIND RIVET AVIBVLB	Necessary	11.00 FS	*11.00 FS
17	3		*SCREW (SF PLUS M5X15)	Not Necessary	1.65 FS	*- FS
18	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	331.80 FS	*331.80 FS
19	19		*PUNCH RIVET N5	Necessary	10.45 FS	*10.45 FS
20	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	114.45 FS	*114.45 FS
21	1		*(DG) CLEANER R1 (100ML) (3 PCS)	Necessary (1 PCS ONLY)	78.45 FS	*26.15 FS
22	3		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary (2 PCS ONLY)	394.65 FS	*263.10 FS
23	20		*PUNCH RIVET N4	Necessary	11.00 FS	*11.00 FS
24	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Necessary	27.85 FS	*27.85 FS
25	1		*(S/L) SEAM SEAL 300ML	Necessary	33.80 FS	*33.80 FS
26	1		*(DG) CLEANER R1 (100ML)	Repeated	26.15 FS	*- FS
27	1		*SNAP LOCK COUPLING	Necessary	3.80 FS	*3.80 FS
28	1		*COVER POT	Cracked	76.50 FS	*76.50 FS
29	3		*HOOK AND LOOP FASTENER	Necessary	8.55 FS	*8.55 FS
30	1		*RR RH SIDE WINDOW (BASIS)	Necessary	293.05 FS	*293.05 FS
31	1		*TYPE IDENTIFICATION PLATE (CODED)	Necessary	29.45 FS	*29.45 FS
32	1		*LABEL TIRE PRESSURE	Necessary	24.50 FS	*24.50 FS
33	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 5,186.45 3,892.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR RH FENDER ,ATTACHMENTS AND REPAIR REAR BUMPER	New	5,950.00	5,100.00
2	TO PAINTING REAR RH FENDER ,REAR BUMPER ,ROOF FRAME AND TAIL PANEL	New	3,114.00	2,808.00
3	TO REMOVE AND INSTALL REAR HAT-TRAY ,REAR SEAT ,CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS	New	873.00	742.00
4	TO REPLACE REAR WINDSCREEN GLASS	New	676.00	676.00
5	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
6	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
7	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	451.00
8	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	94.00	80.00
9	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	451.00
Gross Labour Cost (S\$)			12,021.00	10,533.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >