

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Aug 2020 Edit Reg		27 Aug 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LI KWONG AGENCIES COMPANY , Co. Reg. No.: 21003600A									
Main Claimant: ZULFADLY BIN MOHAMAD ABU BAKAR									
Vehicle Reg. No.: SMJ8722R		Date of Loss: 25/08/2020 16:00 - :59 [87 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6824946365SG		Policy/Cover Note No.: 1900168416 (Comprehensive)							
Vehicle Reg. No. (Insured): GBF4624T		Policy No. (Claimant):							
		Excess:							
Repairer: Merlin Motor & Engineering Works (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-13 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64845225									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Goh, Jeremy-CX] Jeremy.Goh@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 08/09/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMJ8722R (6824946365SG)**
[GBF4624T]

TP

ZULFADLY BIN MOHAMAD ABU BAKAR

Aug 25 2020 4:00PM

[LI KWONG AGENCIES COMPANY]

Merlin Motor & Engineering Works

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/08/20 15:05	General View	Load JPG	☒
2	31/08/20 15:05	General View	Load JPG	☒
3	31/08/20 15:05	General View	Load JPG	☒
4	31/08/20 15:05	General View	Load JPG	☒
5	31/08/20 15:05	General View	Load JPG	☒
6	31/08/20 15:05	General View	Load JPG	☒
7	31/08/20 15:05	General View	Load JPG	☒
8	31/08/20 15:05	General View	Load JPG	☒
9	31/08/20 15:05	General View	Load JPG	☒
10	31/08/20 15:05	General View	Load JPG	☒
11	31/08/20 15:05	General View	Load JPG	☒
12	31/08/20 15:05	General View	Load JPG	☒
13	31/08/20 15:05	General View	Load JPG	☒
14	31/08/20 15:05	General View	Load JPG	☒
15	31/08/20 15:05	General View	Load JPG	☒
16	31/08/20 15:05	Odometer Reading	Load JPG	☒
17	31/08/20 15:05	Chassis Number	Load JPG	☒
18	01/09/20 12:22	Dismantled Parts	Load JPG	☒
19	01/09/20 12:22	Dismantled Parts	Load JPG	☒
20	01/09/20 12:22	Dismantled Parts	Load JPG	☒
21	01/09/20 12:22	Dismantled Parts	Load JPG	☒
22	01/09/20 12:22	Dismantled Parts	Load JPG	☒
23	01/09/20 12:22	Dismantled Parts	Load JPG	☒
24	01/09/20 12:22	Dismantled Parts	Load JPG	☒
25	01/09/20 12:22	Dismantled Parts	Load JPG	☒
26	01/09/20 12:22	Dismantled Parts	Load JPG	☒
27	01/09/20 12:22	Dismantled Parts	Load JPG	☒
28	01/09/20 12:22	Dismantled Parts	Load JPG	☒
29	07/09/20 10:53	After Repair Photo	Load JPG	☒
30	07/09/20 10:53	After Repair Photo	Load JPG	☒
31	07/09/20 10:53	After Repair Photo	Load JPG	☒
32	07/09/20 10:53	After Repair Photo	Load JPG	☒
33	07/09/20 10:53	After Repair Photo	Load JPG	☒
34	07/09/20 10:53	After Repair Photo	Load JPG	☒
35	07/09/20 10:53	After Repair Photo	Load JPG	☒
36	07/09/20 10:53	After Repair Photo	Load JPG	☒
37	07/09/20 10:53	After Repair Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	31/08/20 15:32	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20009098/GQF3S2**Date:** 07/09/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900168416
Claimant Vehicle No :	SMJ8722R	Insured Vehicle No :	GBF4624T
Date of Loss:	25/08/2020	Nature of Claim:	TP
		Claim No:	6824946365SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ8722R	Engine No:	27491030039879
Make & Model:	MERCEDES-BENZ C180, 1.6 (A)	Chassis No:	WDD2040312A833022
Reg. Date:	17/05/2013 (Man. Year: 2013)	Odometer:	195688 km
Colour:	Black		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	27/08/2020	
Date Inspected:	28/08/2020 Inspected At:	Merlin Motor & Engineering Works (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-13 AMK Autopoint Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
4	1		*FRT RH BUMPER FOG LAMP	Cracked	0.00 F	*- F
5	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >