

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20009099/AEA3Q2
Date: 09/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900085732
Claimant Vehicle No :	SML5549J	Insured Vehicle No :	SML842U
Date of Loss:	27/08/2020	Nature of Claim:	TP
		Claim No:	8797541202SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML5549J	Engine No:	2ZR2B43473
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800343915
Reg. Date:	27/05/2019 (Man. Year: 2018)	Odometer:	97372 km
Colour:	Grey		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Gremax 6 mm	Rear Left Side:	Gremax 6 mm
Front Right Side:	Gremax 6 mm	Rear Right Side:	Gremax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,361.55	7,861.74	15,499.81	66.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,570.00	2,470.00	2,100.00	45.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,931.55	10,331.74	17,599.81	63.01
Approved Total (Overridden) (S\$)		8,200.00		

(S\$)	27,931.55	8,200.00	19,731.55	70.64
+ GST 7.00/7.00% (S\$)	1,955.21	574.00	1,381.21	70.64
Nett Amount (S\$)	29,886.76	8,774.00	21,112.76	70.64
+ Loss of Use (10.0 x S\$90.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,681.45		
Global Sum Settlement (S\$)		7,740.00		

INSPECTION

Date of Assignment: 28/08/2020

Date Inspected: 28/08/2020

Estimated Period of Repair: 8.0 days

Inspected At:

Green Forest Automobile Pte Ltd (Kaki Bukit)
 8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki Bukit
 Singapore 415875

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -RH	Distorted	1,450.00 F	*1,225.00 FL
2	1		*FRONT DOOR HANDLE -RH	Not Necessary	155.20 F	*- FL
3	1		*FRONT DOOR -TOP HINGE -RH	Not Necessary	121.25 F	*- FL
4	1		*FRONT DOOR LOWER HINGE -RH	Not Necessary	121.25 F	*- FL
5	1		*FRONT DOOR INNER GEAR -RH	Not Necessary	585.20 F	*- FL
6	1		*FRONT DOOR INNER MOTOR -RH	Not Necessary	755.20 F	*- FL
7	1		*FRONT DOOR INNER LOCK -RH	Damaged	325.20 F	*325.20 FL
8	1		*FRONT DOOR TOP MOULDING -RH	Not Necessary	171.80 F	*- FL
9	1		*FRONT DOOR INNER TRIM BOARD -RH	Not Necessary	955.00 F	*- FL
10	1		*FRONT DOOR INNER RUBBER	Not Necessary	182.25 F	*- FL
11	1		*FRONT DOOR PILLAR -RH	Repair	851.20 F	*- FL
12	1		*FRONT ROCKER PANEL SKIRTING	Deformed	685.20 F	*685.20 FL
13	1		*REAR DOOR -RH	Distorted	1,885.20 F	*1,680.00 FL
14	1		*REAR DOOR HANDLE -RH	Not Necessary	155.20 F	*- FL
15	1		*REAR DOOR TOP HINGES-RH	Not Necessary	131.75 F	*- FL
16	1		*REAR DOOR LOWER HINGES-RH	Damaged	131.75 F	*131.75 FL
17	1		*REAR DOOR INNER LOCK -RH	Damaged	388.20 F	*388.20 FL
18	1		*REAR DOOR INNER TRIM BOARD -RH	Cracked	1,050.20 F	*628.00 FL
19	1		*REAR DOOR INNER GEAR -RH	Damaged	688.20 F	*235.00 FL
20	1		*REAR DOOR INNER GEAR MOTOR -RH	Not Necessary	822.10 F	*- FL
21	1		*REAR DOOR INNER SPONGE -RH	Not Necessary	182.55 F	*- FL
22	1		*REAR DOOR INNER RUBBER -RH	Cut	181.10 F	*181.10 FL
23	1		*REAR DOOR TOP MOULDING -RH	Not Necessary	172.25 F	*- FL
24	1		*REAR R/H FENDER	Repair	2,150.00 F	*- FL
25	1		*REAR FENDER OUTER GARNISH RH	Not Necessary	165.00 F	*- FL
26	1		*REAR R/H FENDER INNER TRIM BOARD	Not Necessary	675.00 F	*- FL
27	1		*REAR FENDER INNER PANEL -RH	Repair	1,250.00 F	*- FL
28	1		*REAR RIM -RH	Cut	650.00 FS	*450.00 FS
29	1		*REAR TYRE -RH	Cut	400.00 FS	*200.00 FS
30	1		*REAR AXLE	Bent	2,648.00 F	*2,648.00 FL
31	1		*REAR WHEEL HUB	Damaged	388.20 F	*388.20 FL
32	1		*REAR SHOCK ABSORBER -RH	Not Necessary	552.10 F	*- FL
33	1		*REAR BUMPER	Deformed	1,688.00 F	*1,025.00 FL
34	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	350.00 F	*- FL
35	1		*REAR BUMPER SIDE BRACKET	O/S Necessary	230.00 F	*75.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR BUMPER SIDE REFLECTOR -RH	Not Necessary	68.00 F	*- FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					23,361.55	10,265.65
- List Item Discount on L Items 0.00/25.00% (\$)					0.00	2,403.91
Total Parts (\$)					23,361.55	7,861.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX REAR FENDER GLASS	New	120.00	0.00
2	GUM	New	50.00	0.00
3	TO REMOVE & REFIX REAR & FRONT RH DOOR FITTINGS	New	400.00	160.00
4	TO REMOVE & REFIX CUSHION	New	120.00	60.00
5	TO REMOVE & REFIX REAR UNDERCARRIAGE	New	280.00	280.00
6	TO CHECK WHEEL ALIGNMENT COMPUTER	New	120.00	80.00
7	TO CHECK WIRING SYSTEM	New	60.00	30.00
8	TUFF KOTE	New	120.00	60.00
9	TOWING CHARGES	New	100.00	0.00
10	PANEL BEATING	New	1,600.00	800.00
11	SPRAY PAINTING	New	1,600.00	1,000.00
Gross Labour Cost (S\$)			4,570.00	2,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >