

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20009101/ASF3Q2

**Date:** 04/11/2020

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00005122007

**Claimant  
Vehicle No :** SLU4213Z

**Insured  
Vehicle No :** SKG4292E

Date of Loss: 27/08/2020

Nature of  
Claim: TP

Claim  
No: SNM20D203070C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU4213Z**

Make & Model: TOYOTA SIENTA, 1.5 (A)

Engine No: 1NZ8320137

Reg. Date: 30/11/2017 (Man. Year: 2017)

Chassis No: NHP1707102862

Colour: White

Odometer: 229497 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,538.65	5,369.25	1,169.40	17.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,520.00	2,080.00	1,440.00	40.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,058.65</b>	<b>7,449.25</b>	<b>2,609.40</b>	<b>25.94</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,900.00</b>		
<b>(S\$)</b>	10,058.65	5,900.00	4,158.65	41.34
<b>+ GST 7.00/7.00% (S\$)</b>	704.11	413.00	291.11	41.34
<b>Nett Amount (S\$)</b>	<b>10,762.76</b>	<b>6,313.00</b>	<b>4,449.76</b>	<b>41.34</b>

### INSPECTION

Date of Assignment: 27/08/2020

Date Inspected: 28/08/2020 Inspected At:

N-51 Automotive Pte Ltd (HQ)  
BLK 2 KAKI BUKIT, #01-17/18 KAKI  
BUKIT AUTOHUB  
Singapore 417921

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Nov 2020)
<b>Parts:</b>	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLU4213Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	750.00 FL	*750.00 FL
2	1		*REAR BUMPER CENTRE PROTECTOR	Deformed	207.00 FL	*207.00 FL
3	2		*REAR BUMPER CORNER BRACKET L/R	Not Necessary	166.20 FL	*- FL
4	1		*REAR BUMPER SIDE PROTECTOR L/R	N/S Cracked	302.00 FL	*151.00 FL
5	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	180.00 FL	*180.00 FL
6	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	25.00 FL	*- FL
7	1		*REAR COMPARTMENT TRAY GARNISH	Cracked	519.00 FL	*360.00 FL
8	1		*REAR COMPARTMENT TRAY GARNISH TOP COVER	Deformed	378.00 FL	*378.00 FL
9	1		*REAR END INNER PANEL	Distorted	607.00 FL	*607.00 FL
10	1		*REAR END OUTER PANEL	Distorted	599.00 FL	*599.00 FL
11	1		*REAR END PANEL ANTENNA SENSOR	Cracked	127.00 FL	*127.00 FL
12	1		*REAR END PANEL INNER TOP GARNISH	Deformed	207.00 FL	*207.00 FL
13	1		*REAR FLOOR INNER TOP TRIM COVER	Cracked	686.00 FL	*425.00 FL
14	1		*REAR LH FENDER INNER TRIM GARNISH	Deformed	709.00 FL	*385.00 FL
15	1		*REAR TAILGATE	Distorted	1,380.00 FL	*1,285.00 FL
16	1		*REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM	Necessary	78.00 FL	*78.00 FL
17	1		*REAR TAILGATE LOGO EMBLEM	Necessary	110.00 FL	*110.00 FL
18	1		*REAR TAILGATE MECHANISM LOCK	Damaged	265.00 FL	*265.00 FL
19	2		*REAR TAILGATE RUBBER GUIDE STOPPER L/R	Not Necessary	38.00 FL	*- FL
20	1		*REAR TAILGATE WEATHER STRIP	Cut	385.00 FL	*385.00 FL
21	2		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	90.00 FL	*90.00 FL
22	2		*REAR TAILGATE WINDSCREEN SEAL	Necessary	90.00 FL	*90.00 FL
23	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
24	1		*REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
25	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
26	2		*SET REAR FENDER INNER TRIM GARNISH CLIPS L/R	Necessary	100.00 FS	*30.00 FS
27	1		*REAR NUMBER PLATE	Not Necessary	25.00 FS	*- FS
28	1		*REAR NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
29	1		*SET REAR TAILGATE INNER TRIM GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
30	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,513.20</b>	<b>7,039.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,974.55</b>	<b>1,669.75</b>
<b>Total Parts (\$\$)</b>	<b>6,538.65</b>	<b>5,369.25</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING ,AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
2	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	150.00	60.00
4	TO RE-SPRAY PAINTING ON THE REAR BOOTLID ,REAR END PANEL,REAR FENDER (L/R) ,SPARE TYRE PANEL AND REAR BUMPER	New	1,600.00	800.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE- ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,400.00	900.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	60.00
7	TO REMOVE ,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	80.00
<b>Gross Labour Cost (\$)</b>			<b>3,520.00</b>	<b>2,080.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >