

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009104/ADA3Q2

Date: 17/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100508609

Claimant
Vehicle No : SML4991X **Insured Vehicle No :** SGV3690P

Date of Loss: 26/08/2020 Nature of Claim: TP Claim No: 7778053436SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML4991X	Engine No:	4B12QS3241
Make & Model:	MITSUBISHI OUTLANDER, 2.4 CVT (A)	Chassis No:	JMYXTGF3WGZ002467
Reg. Date:	18/02/2016 (Man. Year: 2015)	Odometer:	90339 km
Colour:	Red		
Engine Capacity:	2360 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,995.80	5,892.50	12,103.30	67.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,970.00	2,190.00	2,780.00	55.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,965.80	8,082.50	14,883.30	64.81
Approved Total (Overridden) (\$\$)		6,400.00		
(\$\$)	22,965.80	6,400.00	16,565.80	72.13
+ GST 7.00/7.00% (\$\$)	1,607.61	448.00	1,159.61	72.13
Nett Amount (\$\$)	24,573.41	6,848.00	17,725.41	72.13
+ Car Rental (6.0 x S\$120.00/day) (\$\$)		720.00		
+ Doc/Search Fee (\$\$)		36.45		
Nett Liability (\$\$)		7,604.45		
Global Sum Settlement (\$\$)		7,600.00		

INSPECTION

Date of Assignment: 27/08/2020

Date Inspected: 28/08/2020 Inspected At:

Vision Autowork Pte Ltd (HQ)
8 KAKI BUKIT AVE 4,, #08-09
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	884.00 FL	*884.00 FL
2	2		*TAIL GATE LAMP	Cracked	794.00 FL	*794.00 FL
3	1		*TAILGATE LOGO	Necessary	41.00 FL	*41.00 FL
4	1		*TAIL GATE CENTER GARNISH	Cracked	446.00 FL	*446.00 FL
5	1		*TAILGATE EMBLEM OUTLANDER	Necessary	86.00 FL	*86.00 FL
6	1		*TAILGATE EMBLEM 4WD	Necessary	68.00 FL	*68.00 FL
7	1		*TAILGATE INNER LOCK	Damaged	428.00 FL	*428.00 FL
8	1		*TAILGATE WEATHERSTRIP	Cut	192.00 FL	*192.00 FL
9	2		*TAILGATE SIDE SENSOR	Not Necessary	770.00 FL	*- FL
10	2		*TAILGATE STOPPER	Not Necessary	36.00 FL	*- FL
11	1		*TAILGATE INNER TRIM (LOWER)	Cracked	260.00 FL	*260.00 FL
12	2		*TAIL GATE DAMPER	Not Necessary	340.00 FL	*- FL
13	1		*TAIL GATE KEYLESS ECU MODULE	Not Necessary	1,791.00 FL	*- FL
14	1		*TAILGATE DETECTOR WIREHARNES	Not Necessary	498.00 FL	*- FL
15	1		*TAILGATE DETECTOR	Cracked	396.00 FL	*95.00 FL
16	1		*TAILGATE BUZZLE	Cracked	187.00 FL	*90.00 FL
17	1		*TAILGATE WINDSCREEN MOULDING	Necessary	160.00 FL	*160.00 FL
18	1		*REAR BUMPER	Deformed	816.00 FL	*816.00 FL
19	2		*REAR BUMPER SIDE ARCED GARNISH	Not Necessary	588.00 FL	*- FL
20	2		*REAR BUMPER LAMP	Cut	196.00 FL	*196.00 FL
21	1		*REAR BUMPER LAMP WIRE HARNESS	Not Necessary	387.00 FL	*- FL
22	1		*REAR BUMPER LOWER CENTER GARNISH	Deformed	269.00 FL	*269.00 FL
23	2		*REAR BUMPER SIDE RETAINER	Necessary	64.00 FL	*64.00 FL
24	2		*TAIL LAMP	Not Necessary	1,142.00 FL	*- FL
25	2		*REAR FENDER INNER COWLING	Not Necessary	306.00 FL	*- FL
26	2		*REAR FENDER INNER TRIM	Not Necessary	1,854.00 FL	*- FL
27	1		*REAR END PANEL	Dented	496.00 FL	*496.00 FL
28	1		*REAR END PANEL TOP GARNISH	Deformed	146.00 FL	*146.00 FL
29	2		*REAR END ABSORB PANEL	Not Necessary	770.00 FL	*- FL
30	1		*REAR FLOOR PANEL	Repair	714.00 FL	*- FL
31	1		*REAR STORAGE COMPARTMENT COVER	Deformed	675.00 FL	*292.00 FL
32	1		*REAR STORAGE COMPARTMENT GARNISH	Deformed	455.00 FL	*202.00 FL
33	1		*REAR CHASSIS MEMBER RH	Repair	693.00 FL	*- FL
34	1		*REAR SPARE TYRE BRACKET	Not Necessary	386.00 FL	*- FL
35	1		*REAR SPARE TYRE BRACKET HOLDER	Not Necessary	128.00 FL	*- FL
36	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
37	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
38	1		*SET REAR BUMPER SIDE ARCED GARNISH CLIP	Necessary	60.00 FS	*40.00 FS
39	1		*SET REAR BUMPER LOWER CENTER GARNISH CLIP	Necessary	60.00 FS	*20.00 FS
40	1		*TAILGATE SEALANT		150.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Not Necessary		
41	1		*SET TAIL GATE CENTER GARNISH CLIP	Necessary	60.00 FS	*20.00 FS
42	1		*SET TAILGATE INNER TRIM (LOWER) CLIP	Necessary	60.00 FS	*30.00 FS
43	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
44	1		*TAILGATE WINDSCREEN INNER SHIELD	Not Necessary	60.00 FS	*- FS
45	1		*SET TAILLAMP CLIP	Not Necessary	30.00 FS	*- FS
46	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
47	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	60.00 FS	*- FS
48	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
49	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
50	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS
51	1		*SET REAR STORAGE COMPARTMENT GARNISH CLIP	Not Necessary	60.00 FS	*- FS
52	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
53	1		*REVERSE CAMERA	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,742.00	6,495.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,746.20	602.50
Total Parts (\$\$)	17,995.80	5,892.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,600.00	900.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	250.00	80.00
4	WIRING AND BULB CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	80.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
8	REINSTALL AND RESET TAILGATE AUTO SYSTEM SENSOR	New	350.00	0.00
9	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
10	CONDUCT WATER LEAKAGE TEST	New	180.00	0.00
11	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
12	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	200.00	0.00
Gross Labour Cost (S\$)			4,970.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >