

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20009105/KRS3Q2
Date: 11/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070015262
Claimant Vehicle No :	SLQ9210U	Insured Vehicle No :	SJN9699H
Date of Loss:	26/08/2020	Nature of Claim:	TP
		Claim No:	8424998165SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ9210U		
Make & Model:	PEUGEOT 5008, 1.6 (A)	Engine No:	10JBHX3021619
Reg. Date:	27/07/2017 (Man. Year: 2016)	Chassis No:	VF38DBHGTGL046388
Colour:	Metallic Blue	Odometer:	120817 km
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,821.94	10,315.14	506.80	4.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	1,780.00	240.00	11.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,841.94	12,095.14	746.80	5.82
+ GST 7.00/7.00% (S\$)	898.94	846.66	52.28	5.82

Nett Amount (S\$)	13,740.88	12,941.80	799.08	5.82
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		13,303.80		
Global Sum Settlement (S\$)		13,300.00		

INSPECTION

Date of Assignment: 28/08/2020

Date Inspected: 28/08/2020

Estimated Period of Repair: 6.0 days

Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,495.00 FL	*1,495.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	506.00 FL	*506.00 FL
3	1		*REAR BUMPER ABSORBER	Cracked	276.00 FL	*276.00 FL
4	1		*SET REAR BUMPER SIDE RETAINER	Serviceable	276.00 FL	*- FL
5	2		*REAR BUMPER BRACKET	Bent	207.00 FL	*207.00 FL
6	1		*REAR BUMPER LOWER BUMPER	Buckled	460.00 FL	*460.00 FL
7	2		*REAR BUMPER SIDE CHROME MOULDING	Necessary	368.00 FL	*368.00 FL
8	2		*REAR BUMPER NO PLATE LAMP	Dented	82.80 FL	*82.80 FL
9	1		*REAR BUMPER REVERSE CAMERA	Shorted	920.00 FL	*920.00 FL
10	2		*REAR BUMPER INNER CENTRE PDC SENSOR	Shorted (1 PCS ONLY)	552.00 FL	*276.00 FL
11	2		*TAILLAMP	Cracked	2,070.00 FL	*2,070.00 FL
12	1		*REAR BOOT	Bent	1,725.00 FL	*1,725.00 FL
13	1		*REAR BOOT INNER LOCK	Dented	161.00 FL	*161.00 FL
14	1		*REAR BOOT INNER RUBBER	Deformed	207.00 FL	*207.00 FL
15	1		*REAR BOOT CHROME MOULDING	Necessary	633.75 FL	*633.75 FL
16	1		*REAR BOOT OUTER GARNISH	Cracked	690.00 FL	*690.00 FL
17	1		*REAR BOOT LOGO & EMBLEM PEUGEOT	Necessary	103.50 FL	*103.50 FL
18	2		*REAR BOOT STOPPER	Missing	46.00 FL	*46.00 FL
19	1		*REAR END PANEL	Bent	828.00 FL	*828.00 FL
20	1		*REAR END PANEL INNER TOP GARNISH	Mtg Distorted	276.00 FL	*276.00 FL
21	1		*REAR BUMPER EMBLEM 508	Necessary	58.00 FL	*58.00 FL
22	1		*REAR END PANEL SEALANT	Necessary	40.00 FS	*30.00 FS
23	1		*REAR NUMBER PLATE	Dented	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,016.05	11,454.05
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,194.11	1,138.91
Total Parts (\$\$)	10,821.94	10,315.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX REAR BUMPER ,LWER BUMPER & ATTACHMENTS ,PARKING SENSORS ,REAR BOOT & ATTACHMENTS ,TAILLAMP TO CUT ,WELD & RENEW REAR END PANEL,KNOCKING & REPAIR REAR SPARE TYRE PANEL & REALIGN THE SAME	New	900.00	800.00
2	PUTTY & RESPRAY REAR BUMPER ,PARKING SENSOR ,REAR BOOT & OUTER GARNISH ,REAR END PANEL,REAR SPARE TYRE PANEL ,FENDERS & ALL AFFECTED AREAS	New	900.00	800.00
3	REMOVE & REFIX PAKING SENSORS CHECK & RESET SYSTEM	New	80.00	60.00
4	REMOVE & REFIX REVERSE CAMERA & CHECK & REALIGN THE SAME	New	60.00	60.00
5	RUSTPROOFING	New	80.00	60.00
Gross Labour Cost (S\$)			2,020.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >