

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110 INV No. AC2006657

INV Date 25/09/2020

Reference CC6/EQI20009115/Uga3q2

Code EQ



PROFESSIONAL SERVICE FEE

Vehicle No. SGW 4192Z Insured Veh. SMC 9936X

Claim No. DM20HO01261-JG

Policy No. DMPPHQ20-004403

Accident Date 27/08/2020

Inspection Date 28/08/2020

| Description | Total |
|--------------------------------|--------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (7%) | 28.00 |
| Grand Total | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

| | Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|---|---|---------------------|------------|--|
| EQ INSURANCE COMPANY LTD Ref: CC6/EQI20009115/U | | | 5/Uga3q2 | | |
| 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110 | | Date: 25-09-2020 | | | |
| | | | Code: EQI | | |
| 1. | | | - THIRD PARTY CLAIM | | |
| | sured Veh. | SMC 9936X | Veh. Inspected | SGW 4192Z | |
| \vdash | licy No. | DMPPHQ20-004403 | Coverage (\$) | 0.00 | |
| | aim No. | DM20HO01261-JG | Excess (\$) | 0.00 | |
| As | sign From | | Assign Date | 28/08/2020 | |
| 2. | | Vehicle Partic | culars & Condition | | |
| Ма | ike & Model | TOYOTA VIOS (M) | c.c | 1497 | |
| En | gine No. | HIDDEN | Year of Reg. | 2007 | |
| Ch | assis No. | MR053HY9305008320 | Colour | BEIGE | |
| Od | lometer | 186795 | Steering | IN ORDER | |
| Bra | akes | IN ORDER | Modification | SPORTS RIM | |
| Ge | neral | GOOD | | | |
| 3. | | Condition | ons of Tyres | | |
| | | Size | Make | Balance | |
| R/H | H Front Tyre | 195/55 R15 | MICHELIN | 6 mm | |
| L/F | I Front Tyre | 195/55 R15 | MICHELIN | 6 mm | |
| R/H | H Rear Tyre | 195/55 R15 | MICHELIN | 6 mm | |
| L/F | l Rear Tyre | 195/55 R15 | MICHELIN | 6 mm | |
| 4. | Description of Damages | | | | |
| THI | E VEHICLE SUS | STAINED DAMAGES AT THE REA | AR N/S PORTION. | | |
| DA | MAGES SEE DI | ETAILS. | | | |
| 5. | | General | Information | | |
| Ac | cident Date | 27/08/2020 | Inspection Date | 28/08/2020 | |
| Su | rvey held at | FASTECH AUTO PTE LTD | | | |
| | | 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 | | | |
| 5a. | | Re | emarks | | |
| A)T B)II | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | b. Estimate Days of Repair | | | | |
| ES. | TIMATED NORI | MAL PERIOD FOR REPAIR: | 4 Working Days | | |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGW 4192Z

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------------------|-------------------------------|----------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | BOOTLID | DENTED / BUCKLED | 766.50 | 566.10 |
| 1 | BOOTLID OUTER HANDLE | NOT NECESSARY | 198.10 | - |
| 1 | BOOTLID REAR LOGO | NECESSARY | 60.80 | 60.80 |
| 1 | BOOTLID INNER LOCK | SHORTED | 199.40 | 185.40 |
| 1 | BOOTLID LOCK STRIKER | NOT NECESSARY | 89.90 | - |
| 1 | BOOTLID WEATHERSTRIP | TWISTED | 266.50 | 198.70 |
| 1 | REAR BUMPER | DENTED | 655.10 | 427.90 |
| 2 | REAR BUMPER SIDE RETAINERS @\$76.50 | NOT NECESSARY | 153.00 | - |
| 2 | REAR BUMPER BRACKETS @\$99.10 | NOT NECESSARY | 198.20 | - |
| 2 | REAR BUMPER REFLECTORS @\$195.00 | N/S CRACKED | 390.00 | 151.00 |
| 1 | SET REAR BUMPER CLIPS | NECESSARY | 50.00 | 50.00 |
| 1 | REAR EXHAUST | NOT NECESSARY | 588.10 | - |
| 2 | REAR EXHAUST MOUNTINGS @\$65.00 | NOT NECESSARY | 130.00 | - |
| 1 | REAR END PANEL | DENTED / BENT | 655.20 | 601.10 |
| 1 | REAR END PANEL GARNISH | TWISTED | 315.10 | 165.80 |
| 2 | TAILLAMPS @\$520.10 | N/S CRACKED | 1,040.20 | 322.50 |
| 2 | TAILLAMPS HOUSING PANELS @\$199.50 | TO REPAIR SEE LABOUR | 399.00 | - |
| 1 | REAR FLOOR PANEL | TO REPAIR SEE LABOUR | 911.20 | - |
| 1 | REAR FLOOR PANEL TOP BOARD | TORN | 422.50 | 299.20 |
| 2 | REAR FLOOR PANEL SIDE TOOLS SPONGES @\$389.10 | N/S TORN | 778.20 | 302.20 |
| 2 | REAR FENDERS @\$845.10 | NOT NECESSARY | 1,690.20 | - |
| 2 | REAR FENDER INNER SPLASH SHIELDS @\$105.00 | N/S TOEN | 210.00 | 102.10 |
| | LESS 25% DISCOUNT | | - | -858.20 |
| | | | 10,167.20 | 2,574.60 |
| | SPECIAL NETT ITEMS | | | |
| 1 | SET REAR BUMPER REVERSE SENSOR (SN) | SHORTED | 280.00 | 200.00 |
| 1 | REAR END PANEL SEALANT (SN) | NECESSARY | 50.00 | 50.00 |

Report Ref No. CC6/EQI20009115/Uga3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

3,700.00

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|---------------|----------------------------|-------------------|
| 1 | REAR FLOOR PANEL INSULATOR (SN) | NOT NECESSARY | 200.00 | - |
| | | | 530.00 | 250.00 |
| | <u>LABOUR</u> | | | |
| | TO CHECK WIRING. | | 80.00 | 20.00 |
| | TO DISMANTLE & REPLACING REVERSE SENSOR. | | 80.00 | 50.00 |
| | TO TRANSFER BOOTLID MECHANISM. | | 80.00 | 60.00 |
| | TO SPRAY RUST PROOFING. | | 120.00 | 60.00 |
| | TO DISMANTLE & REFIX REAR EXHAUST. | NOT NECESSARY | 100.00 | - |
| | TO DISMANTLE & REFIX CUSHION UPHOLSTERY. | | 180.00 | 80.00 |
| | LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMPS HOUSING PANELS AND REAR FLOOR PANEL. | | 1,800.00 | 650.00 |
| | TO PUTTY & SPRAY PAINTING. | | 1,680.00 | 900.00 |
| | | | 4,120.00 | 1,820.00 |
| | GRAND TOTAL | | 14,817.20 | 4,644.60 |

Report Ref No. CC6/EQI20009115/Uga3q2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

CHUA KANG SENG

Licensed Appraiser




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGW 4192Z



















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGW 4192Z











