



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GX 6548M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DENTED / SQUASHED / TORN	452.10	452.10
1	FRONT BUMPER SIDE RETAINER L/R	NECESSARY	32.20	32.20
10	FRONT BUMPER RETAINING CLIP	NECESSARY	55.00	55.00
	LESS 25% DISCOUNT		-134.83	-134.83
			404.47	404.47
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	BENT / DISTORTED	35.00	35.00
			35.00	35.00
<u>LABOUR</u>				
	TO CHECK WIRING AT THE AFFECTED AREAS FOR CONDITION AND REPAIR WHERE NEEDED.		45.00	30.00
	PANEL BEATING CHARGES TO DISMANTLE AND REMOVE ALL DAMAGED PARTS, RENEW AND INSTALL THE SAME; TO CUT OUT THE DAMAGED BODY, RENEW AND WELD THE SAME; TO KNOCK AND RESHAPE SURROUNDING PANELS BACK TO SHAPE AND ALIGNMENT.		900.00	400.00
	SPRAY PAINT ALL AFFECTED PARTS AND REPAIRED AREAS.		350.00	250.00
			1,295.00	680.00
GRAND TOTAL			1,734.47	1,119.47
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				900.00

Report Ref No. CS3/LPC20006818/R1vf3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.