

8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 185M0720.MAS
Vehicle no: GX6548M

A SPARE PARTS

<u>Description</u>	<u>Qty</u>	<u>Assessed Condition</u>	<u>Repairer's Amount</u>	<u>Revised Amount</u>
Front bumper	1	dented/squashed/torn	452.10	452.10
Front bumper side retainer L/R	1	necessary	32.20	32.20
Front bumper retaining clip	10	necessary	55.00	55.00
		Subtotal of the above	539.30	539.30
		Discount 25%	134.83	134.83
(Special nett)		Subtotal 1:	404.48	404.48
Front number plate	1	bent/distorted	35.00	35.00
		Subtotal 2:	35.00	35.00
		Total cost of parts:	439.48	439.48

B LABOUR

To check wiring at the affected areas for condition and repair where needed.

	45.00	30.00
Panel beating charges to dismantle and remove all damaged parts, renew and install the same; to cut out the damaged body, renew and weld the same; to knock and reshape surrounding panels back to shape and alignment.	900.00	600.00

Spray paint all affected parts and repaired areas.

	350.00	250.00
Total cost of labour:	1,295.00	880.00

Total cost of repair:

1,734.48	1,319.48
----------	----------

9 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is

\$1,319.48

(a) The recommended cost of repair based on lump sum repairs would be

\$1,100.00

(b) The estimated number of days taken for the repairs would be
(1st Reinspection conducted on 2 July 2020)

(Post Repair Inspection conducted on 6 July 2020)

Five (5)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Note: Lump Sum Repair Basis

This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.

Prepared by:

404.48
35.00
680.00

1119.48

20%

Lliao Leong San

Licensed Automotive Appraiser

895

L/S - 900

Dated: 21 July 2020

4 days