



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 8977S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	HANDLE BAR	BENT	189.00	172.00
1	SET HANDLE BAR BALANCER L/R	NOT NECESSARY	40.00	-
1	SET HAND GUARD L/R	NOT NECESSARY	180.00	-
1	BRAKE LEVER	NOT NECESSARY	58.00	-
1	CLUTCH LEVER	CUT	58.00	58.00
1	METER ASSY	NOT WORKING	680.00	480.00
1	FRONT WINDSHIELD	SCRATCHED	385.00	200.00
1	HEADLAMP COWLING	NOT NECESSARY	257.00	-
1	FRONT SHIELD	CUT	108.00	108.00
1	HEADLAMP ASSY	CRACKED	859.00	617.00
1	FRONT COWLING STAY	BENT	157.00	65.00
2	VIEW MIRROR L/R @\$216.00	N/S CUT / O/S NOT NECESSARY	432.00	45.00
1	FUEL TANK LID	NOT NECESSARY	280.00	-
2	FUEL TANK SIDE COVER L/R @\$418.00	NOT NECESSARY	836.00	-
1	SET FRONT SIDE COWLING EMBLEM L/R	NOT NECESSARY	58.00	-
2	FRONT INNER SHROUD L/R @\$245.00	N/S CUT / O/S NOT NECESSARY	490.00	55.00
2	FRONT SIDE COWLING L/R @\$315.00	N/S CUT / O/S NOT NECESSARY	630.00	95.00
2	FRONT SIDE COVER L/R (SILVER) @\$157.00	NOT NECESSARY	314.00	-
2	FRONT SIDE LAMP L/R @\$135.00	N/S CUT / O/S NOT NECESSARY	270.00	35.00
2	FRONT FORK TUBE ASSY L/R @\$890.00	BENT	1,780.00	400.00
2	FRONT FORK TUBE GUARD L/R @\$68.00	NOT NECESSARY	136.00	-
1	FRONT LOWER STEERING STEM	BENT	385.00	80.00
1	FRONT WHEEL RIM	BENT	849.00	295.00
1	FRONT BRAKE DISC	NOT NECESSARY	540.00	-
1	FRONT FENDER	CUT	216.00	160.00
1	REAR BRAKE PEDAL	NOT NECESSARY	95.00	-
1	FRONT FOOTREST LH	BROKEN	58.00	40.00
1	FRONT FOOTREST BRACKET LH	NOT NECESSARY	285.00	-

Report Ref No. CS/AWA20009121/Gvf3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FOOTREST LH	NOT NECESSARY	45.00	-
1	REAR FOOTREST BRACKET LH	NOT NECESSARY	185.00	-
	LESS 10% DISCOUNT		-1,085.50	-290.50
			9,769.50	2,614.50
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT RIM BEARING & OIL SEAL (SN)	NECESSARY	55.00	30.00
1	SET STEERING CONE UPPER/LOWER BEARING (SN)	NECESSARY	68.00	40.00
1	SET ENGINE CRASH BAR L/R (SN)	CUT	380.90	120.00
1	FRONT NUMBER STICKER (SN)	SCRATCHED	20.00	10.00
2	FORK OIL SEAL & DUCT COVER L/R @\$38.00 (SN)	NECESSARY	76.00	40.00
2	BOTS FORK OIL @\$15.00 (SN)	NECESSARY	30.00	20.00
1	REAR STORAGE BOX (SN)	SCRATCHED	450.00	150.00
			1,079.90	410.00
	<b><u>LABOUR</u></b>			
	TOWING SERVICE CHARGE (2 TRIPS).		80.00	50.00
	FRONT BODY FRAME ALIGNMENT.	NOT NECESSARY	380.00	-
	REPLACE,REALIGN & ADJUST ABOVE DAMAGED PARTS.CHECK WIRING,RE-CONNECTION & LIGHTING SYSTEM.		450.00	400.00
			910.00	450.00
	<b>GRAND TOTAL</b>		<b>11,759.40</b>	<b>3,474.50</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (UN-CONFIRMED)</b>			<b>2,750.00</b>

Report Ref No. CS/AWA20009121/Gvf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.